

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **17-3244**
 Date of Acc: **05/15/17**
 Time of Acc: **16:05** Hrs.
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**
 Officer: **STEHR MICHAEL**
 Badge #: **47-9**
 Report Date: **05/15/2017**
 Officer Notified: **16:05** Hrs.
 Officer Arrived: **16:07** Hrs.
 Scene Investigated: **YES**

Report to All Drivers: **YES**
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **IDA - 47**
 Acc Loc City: **IDA GROVE - 3650**
 Acc Dir From City: **"N/A"**
 Closest City: **"N/A"**
 Miles From City: **"N/A"**
 Road, Street, HWay: **"N/A"**
 Definable Location: **"N/A"**
 Milepost Number: **"N/A"**

At Intersection with: **"N/A"**
 Div HWay Trvl Dir: **"N/A"**
 Distance 1: **"N/A"**
 Direction 1: **"N/A"**
 Distance 2: **"N/A"**
 Direction 2: **"N/A"**
 X-Coordinate: **00294900**
 Y-Coordinate: **04690672**
 Location Literal: **HUGHES LN**
 Description:

Unit 001

Driver Name - Last: HOFFMAN	Bus Use:	Transported to:	N/A
First: KELLY		Transported by:	N/A
Middle: LOUISE	Drvr Distractions: 11 - UNRESTRAINED ANIMAL	Special Veh Func:	01 - NO SPECIAL FUNCTION
City: IDA GROVE	Traffic Controls: 01 - NO CONTROLS PRESENT	Emergency Status:	01 - NOT APPLICABLE
State: IA	Point of Init Impact: 05 - REAR PASSENGER SIDE CORNER	Cont. Circum., Drvr:	45 - FTYROW: FROM PARKED POSITION
Zip: 51445-0000	Most Damaged Area: 05 - REAR PASSENGER SIDE CORNER	Carrier Name:	
Suffix:	Undrrid/Ovrid: 1 - NONE	Carrier Address:	
Gender: Female	Rpr/Rplc Cost: \$500.00	Carrier City:	
Age: 55	Ext of Damage: 2 - MINOR DAMAGE	Carrier State:	
CDL: NO	First Event: 35 - PARKED MOTOR VEHICLE	Carrier Zip:	
License State: IA	Second Event:	Cargo Body Type:	01 - NOT APPLICABLE
License Class: C	Third Event:	Number of Axles:	
License Endorsmnt: NONE	Fourth Event:	HazMat Involvement:	
License Restrictions: NONE	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	HazMat Placard:	
Speed Limit: 20	Abg Switch Stat:	Placard #:	
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy: 01 - NOT APPLICABLE	HazMat Released?:	
Driver Condition: 01 - APPARENTLY NORMAL	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:	
Alcohol Test Given: NO	Ejection: 1 - NOT APPLICABLE	GVWR:	
Drug Test Given: 1 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1:	
Total Occupants: 1	Occpnt Protect: 99 - UNKNOWN	Citation Charge 1:	
Vehicle Year: 2016	Injury Status: 5 - UNINJURED	Cit Chrg Code 2:	
Vehicle Make: CHEVROLET - CHEV	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 2:	
Vehicle Model: EQX	Died at Scene: 01 - NOT APPLICABLE	Cit Chrg Code 3:	
Vehicle Style: SW		Citation Charge 3:	
Vehicle Color: GRAY - GRY		Cit Chrg Code 4:	
Vehicle Config: 03 - SPORT UTILITY VEHICLE		Citation Charge 4:	
Vehicle Defect: 01 - NONE			
Vehicle Action: 09 - BACKING			
Tow: 1 - DRIVEN AWAY			
Tow #:			
Initial Trvl Dir: 03 - SOUTH			
Vision Obscured: 01 - NOT OBSCURED			

Unit 002

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:		
State:	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip:		
Suffix:	Point of Init Impact: 10 - FRONT DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender:	Most Damaged Area: 10 - FRONT DRIVER SIDE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age:	Undridd/Ovrid: 1 - NONE	
CDL:	Rpr/Rplc Cost: \$100.00	
License State:	Ext of Damage: 1 - NONE	
License Class:	First Event: 35 - PARKED MOTOR VEHICLE	
License Endorsmnt: NONE		Carrier Name:
License Restrictions: NONE		Carrier Address:
Speed Limit: 20		Carrier City:
Seating Position:	Second Event:	Carrier State:
		Carrier Zip:
Driver Condition:	Third Event:	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given:		
Drug Test Given:	Fourth Event:	
Total Occupants:		Number of Axles:
Vehicle Year: 2005	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	HazMat Involvement:
Vehicle Make: PONTIAC - PONT		HazMat Placard:
Vehicle Model: GRA		Placard #:
Vehicle Style: 4D		HazMat Released?:
Vehicle Color: TURQUOISE (BLUE) - TRQ	Abg Switch Stat:	Converter Dolly:
Vehicle Config: 01 - PASSENGER CAR	Abg Deploy:	GVWR:
Vehicle Defect: 01 - NONE	Trapped:	Cit Chrg Code 1:
	Ejection:	Citation Charge 1:
Vehicle Action: 12 - LEGALLY PARKED	Ejection Path:	
		Cit Chrg Code 2:
Tow: 1 - DRIVEN AWAY	Occpnt Protect:	Citation Charge 2:
Tow #:	Injury Status:	Cit Chrg Code 3:
Initial Trvl Dir:		Citation Charge 3:
Vision Obscured:	Source of Trans:	
	Died at Scene:	Cit Chrg Code 4:
		Citation Charge 4:

Accident Environment

First Harmful Event Loc: 02 - SHOULDER	Roadway Characteristics
Manner of Crash/Collision: 09 - REAR TO SIDE	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 35 - PARKED MOTOR VEHICLE
Type:	
Workers Present:	

Narrative

UNIT 1 WAS BACKING OUT OF A PRIVATE DRIVEWAY ONTO THE STREET. UNIT 2 WAS LEGALLY PARKED ON THE STREET. UNIT 1 DID BACK UP AND STRUCK UNIT 2 IN THE FRONT DRIVERS QUARTER PANEL AREA OF THE VEHICLE CAUSING MINOR DAMAGE TO BOTH VEHICLES. DRIVER OF UNIT 1 ADVISED SHE DID NOT SEE UNIT 2. UNIT 1 DRIVER ADVISED SHE HAD A LOOSE DOG IN THE VEHICLE WHICH COULD HAVE MADE THE DRIVER DISTRACTED.

