

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 17-8421	Report to All Drivers: YES	At Intersection with:
Date of Acc: 11/24/17	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 06:00 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
Officer: ANDERSON FRED	Acc Loc City:	Distance 2:
Badge #: 47-2	Acc Dir From City:	Direction 2:
Report Date: 11/24/2017	Closest City:	X-Coordinate: 00302238
Officer Notified: 07:35 Hrs.	Miles From City:	Y-Coordinate: 04690026
Officer Arrived: 07:50 Hrs.	Road, Street, HWay:	Location Literal: NOBLE AVE AND STATE
Scene Investigated: NO	Definable Location:	Description: 175/IOWA 175
	Milepost Number:	

Unit 001

Driver Name - Last: OXENDALE	Bus Use:	Transported to:
First: TERRY		
Middle: LEE	Drvtr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City: ARTHUR	Traffic Controls:	Special Veh Func:
State: IA	Point of Init Impact:	Emergency Status:
Zip: 51431	Most Damaged Area:	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Suffix:	Undrrid/Ovrid:	
Gender: Male	Rpr/Rplc Cost: \$4,000.00	Carrier Name:
Age: 56	Ext of Damage:	Carrier Address:
CDL: YES	First Event:	Carrier City:
License State: IA	Second Event:	Carrier State:
License Class: A	Third Event:	Carrier Zip:
License Endorsmnt: LN	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions:	Most Harmful Event:	Number of Axles:
Speed Limit:	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
Driver Condition:	Trapped:	Placard #:
Alcohol Test Given: NO	Ejection:	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path:	Converter Dolly:
Total Occupants: 1	Occpnt Protect:	GVWR:
Vehicle Year: 2011	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Make: CHEVROLET - CHEV	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Model: SILVERADO		Citation Charge 2:
Vehicle Style: PU		Citation Charge 3:
Vehicle Color: RED - RED		Citation Charge 4:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)		
Vehicle Defect:		
Vehicle Action:		
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir:		
Vision Obscured:		

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

UNIT #1 WAS WESTBOUND ON HIGHWAY 175 APPROACHING NOBLE AVENUE. A DEER ENTERED THE ROADWAY FROM THE NORTH. UNIT #1 COLLIDED WITH THE DEER CAUSING PASSENGER FRONT AND SIDE DAMAGE. ALL AIRBAGS WERE DEPLOYED.

