

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 17-8455	Report to All Drivers: YES	At Intersection with:
Date of Acc: 11/25/17	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 13:26 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
	Acc Loc City: HOLSTEIN - 3515	Distance 2:
Officer: TRUCKE COREY	Acc Dir From City:	Direction 2:
	Closest City:	X-Coordinate: 00290864
Badge #: 47-6	Miles From City:	Y-Coordinate: 04707240
Report Date: 11/25/2017	Road, Street, HWay:	Location Literal: E 2ND ST AND US 59/N MAIN ST
Officer Notified: 13:26 Hrs.	Definable Location:	Description: AND W 2ND ST AND US 59/S
Officer Arrived: 13:53 Hrs.	Milepost Number:	MAIN ST
Scene Investigated: YES		

Unit 001

Driver Name - Last: WERNER	Bus Use:	Transported to:
First: MATTHEW		
Middle: DEANE	Drvtr Distractions: 02 - NOT DISTRACTED	Transported by:
City: HOLSTEIN	Traffic Controls: 02 - TRAFFIC SIGNALS	Special Veh Func: 01 - NO SPECIAL FUNCTION
State: IA	Point of Init Impact: 15 - NON-COLLISION/NO DAMAGE	Emergency Status: 01 - NOT APPLICABLE
Zip: 51025	Most Damaged Area: 15 - NON-COLLISION/NO DAMAGE	Cont. Circum., Drvr: 98 - OTHER (EXPLAIN IN NARRATIVE)
Suffix:	Undrrid/Ovrid: 1 - NONE	
Gender: Male	Rpr/Rplc Cost: \$0.00	Carrier Name:
Age: 35	Ext of Damage: 1 - NONE	Carrier Address:
CDL: YES	First Event: 35 - PARKED MOTOR VEHICLE	Carrier City:
License State: IA	Second Event:	Carrier State:
License Class: A	Third Event:	Carrier Zip:
License Endorsmnt:	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions:	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	Number of Axles:
Speed Limit: 25	Abg Switch Stat:	HazMat Involvement:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Abg Deploy: 01 - NOT APPLICABLE	HazMat Placard:
Driver Condition: 01 - APPARENTLY NORMAL	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Alcohol Test Given: NO	Ejection: 2 - NOT EJECTED	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Total Occupants: 1	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	GVWR:
Vehicle Year: 2000	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Make: PETERBILT - PTRB	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Model: 379		Cit Chrg Code 2:
Vehicle Style: DS		Citation Charge 2:
Vehicle Color: GRAY - GRY		Citation Charge 3:
Vehicle Config: 11 - TRUCK/TRAILER		Citation Charge 4:
Vehicle Defect: 01 - NONE		
Vehicle Action: 03 - TURNING RIGHT		
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir: 01 - NORTH		
Vision Obscured: 01 - NOT OBSCURED		

Unit 002

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:		
State:	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip:		
Suffix:	Point of Init Impact: 07 - REAR DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender:		
Age:	Most Damaged Area: 07 - REAR DRIVER SIDE CORNER	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
CDL:	Undridd/Ovrid: 1 - NONE	
License State:	Rpr/Rplc Cost: \$1,400.00	
License Class:	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Endorsmnt:	First Event: 35 - PARKED MOTOR VEHICLE	
License Restrictions:		Carrier Name:
Speed Limit: 25		Carrier Address:
Seating Position:	Second Event:	Carrier City:
		Carrier State:
Driver Condition:	Third Event:	Carrier Zip:
Alcohol Test Given:		Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given:	Fourth Event:	
Total Occupants: 0		Number of Axles:
Vehicle Year: 1999		HazMat Involvement:
Vehicle Make: BUICK - BUIC		HazMat Placard:
Vehicle Model: PARK AVENUE		Placard #:
Vehicle Style: PC	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	HazMat Released?:
Vehicle Color: BEIGE - BGE		Converter Dolly:
Vehicle Config: 01 - PASSENGER CAR	Abg Switch Stat:	GVWR:
	Abg Deploy:	Cit Chrg Code 1:
Vehicle Defect: 01 - NONE		Citation Charge 1:
Vehicle Action: 12 - LEGALLY PARKED	Trapped:	
	Ejection:	
Tow: 1 - DRIVEN AWAY	Ejection Path:	Cit Chrg Code 2:
		Citation Charge 2:
Tow #:	Occpnt Protect:	
Initial Trvl Dir: 99 - UNKNOWN		Citation Charge 3:
Vision Obscured:		
	Source of Trans:	
	Died at Scene:	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 98 - OTHER (EXPLAIN IN NARRATIVE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 35 - PARKED MOTOR VEHICLE
Workers Present:	

Narrative

Unit 2 was legally parked on the south side of 2nd Street just east of Main in Holstein, Iowa. Unit 2 was parked in the handicapped spot. Unit 2 was parked several feet away from the curb. Unit 1 was making a right hand turn onto 2nd Street from Main. Unit 1 is a semi that was hauling a dozer. The blade of the dozer struck the trunk of unit 2, causing functional damage. The driver of unit 1 reported this to law enforcement. Unit 2's driver came back to her vehicle and was advised of the accident, but was apparently confused and left the accident scene. Photographs were taken later after both vehicles were moved from the scene.

NOT TO SCALE

