

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 17-8781	Report to All Drivers:	At Intersection with:
Date of Acc: 12/06/17	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 06:48 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
Officer: VAN EGDOM BRADY	Acc Loc City:	Distance 2:
Badge #: 47-5	Acc Dir From City:	Direction 2:
Report Date: 12/06/2017	Closest City:	X-Coordinate: 00300689
Officer Notified: 06:48 Hrs.	Miles From City:	Y-Coordinate: 04692925
Officer Arrived: 06:48 Hrs.	Road, Street, HWay:	Location Literal: M025/MARKET AVE
Scene Investigated: YES	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: EVELAND	Bus Use:	Transported to:
First: CHASE		
Middle: HUNTER	Drvtr Distractions: 02 - NOT DISTRACTED	Transported by:
City: WHITE CLOUD	Traffic Controls:	Special Veh Func:
State: MI	Point of Init Impact:	Emergency Status:
Zip: 49349	Most Damaged Area:	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Suffix:	Undrrid/Ovrid:	
Gender: Male	Rpr/Rplc Cost: \$5,000.00	Carrier Name:
Age: 23	Ext of Damage:	Carrier Address:
CDL: NO	First Event:	Carrier City:
License State: MI	Second Event:	Carrier State:
License Class: R	Third Event:	Carrier Zip:
License Endorsmnt:	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions:	Most Harmful Event:	Number of Axles:
Speed Limit:	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
Driver Condition:	Trapped:	Placard #:
Alcohol Test Given: NO	Ejection:	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path:	Converter Dolly:
Total Occupants: 1	Occpnt Protect:	GVWR:
Vehicle Year: 2003	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Make: BUICK - BUIC	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Model: LESABRE		Citation Charge 2:
Vehicle Style: 4D		Citation Charge 3:
Vehicle Color: GRAY - GRY		Citation Charge 4:
Vehicle Config: 01 - PASSENGER CAR		
Vehicle Defect:		
Vehicle Action:		
Tow: 3 - DISABLED - OFFICER ARRANGED		
Tow #: 17-102		
Initial Trvl Dir:		
Vision Obscured:		

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

UNIT 1 WAS DRIVING NORTH ON MARKET AVENUE. 2 DEER EXITED THE WEST DITCH AND ENTERED THE ROADWAY. UNIT 1 SWERVED TO AVOID THE DEER, MISSING THE 1ST DEER. UNIT 1 WAS UNABLE TO AVOID THE 2ND DEER, STRIKING THE DEER WITH THE DRIVERS SIDE OF THE VEHICLE. UNIT 1 WAS UNABLE TO REGAIN CONTROL OF THE VEHICLE AND THE VEHICLE SLID INTO THE WEST DITCH. UNIT 1 CAME TO A REST IN THE WEST DITCH, FACING EAST. UNIT 1 SUSTAINED DAMAGE FROM STRIKING THE DEER AND FROM ENTERING THE DITCH. UNIT 1 WAS DISABLED AND HAD TO BE TOWED FROM THE SCENE.

Diagram

