

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number:	<b>17-9091</b>	Report to All Drivers:		At Intersection with:	
Date of Acc:	<b>12/18/17</b>	Legal Intervention:	<b>NO</b>	Div HWay Trvl Dir:	
Time of Acc:	<b>19:34</b> Hrs.	Private Property:	<b>NO</b>	Distance 1:	
Name of Agency:	<b>IDA COUNTY SHERIFF'S OFFICE</b>	County:	<b>IDA - 47</b>	Direction 1:	
Officer:	<b>STEHR MICHAEL</b>	Acc Loc City:		Distance 2:	
Badge #:	<b>47-3</b>	Acc Dir From City:		Direction 2:	
Report Date:	<b>12/18/2017</b>	Closest City:		X-Coordinate:	<b>00294030</b>
Officer Notified:	<b>19:34</b> Hrs.	Miles From City:		Y-Coordinate:	<b>04705535</b>
Officer Arrived:	<b>19:34</b> Hrs.	Road, Street, HWay:		Location Literal:	<b>US 20 AND HARVEST AVE</b>
Scene Investigated:	<b>NO</b>	Definable Location:		Description:	
		Milepost Number:			

**Unit 001**

Driver Name - Last:	<b>GUGAT</b>	Bus Use:		Transported to:	<b>N/A</b>
First:	<b>JERRY</b>	Dvrv Distractions:	<b>02 - NOT DISTRACTED</b>	Transported by:	<b>N/A</b>
Middle:	<b>RICHARD</b>	Traffic Controls:	<b>01 - NO CONTROLS PRESENT</b>	Special Veh Func:	<b>01 - NO SPECIAL FUNCTION</b>
City:	<b>SIOUX CITY</b>	Point of Init Impact:	<b>11 - FRONT DRIVER SIDE CORNER</b>	Emergency Status:	<b>01 - NOT APPLICABLE</b>
State:	<b>IA</b>	Most Damaged Area:	<b>11 - FRONT DRIVER SIDE CORNER</b>	Cont. Circum., Dvrv:	<b>88 - NO IMPROPER ACTION</b>
Zip:	<b>51104-0000</b>	Undridd/Ovrid:	<b>1 - NONE</b>	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	<b>\$5,000.00</b>	Carrier Address:	
Gender:	<b>Male</b>	Ext of Damage:	<b>2 - MINOR DAMAGE</b>	Carrier City:	
Age:	<b>48</b>	First Event:	<b>30 - THROWN OR FALLING OBJECT</b>	Carrier State:	
CDL:	<b>YES</b>	Second Event:		Carrier Zip:	
License State:	<b>IA</b>	Third Event:		Cargo Body Type:	<b>05 - FLATBED</b>
License Class:	<b>A</b>	Fourth Event:		Number of Axles:	
License Endorsmnt:	<b>N - TANK</b>	Most Harmful Event:	<b>30 - THROWN OR FALLING OBJECT</b>	HazMat Involvement:	
License Restrictions:		Abg Switch Stat:		HazMat Placard:	
Speed Limit:	<b>55</b>	Abg Deploy:	<b>01 - NOT APPLICABLE</b>	Placard #:	
Seating Position:	<b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Trapped:	<b>1 - NOT TRAPPED/APPLICABLE</b>	HazMat Released?:	
Driver Condition:	<b>01 - APPARENTLY NORMAL</b>	Ejection:	<b>1 - NOT APPLICABLE</b>	Converter Dolly:	
Alcohol Test Given:	<b>NO</b>	Ejection Path:	<b>01 - NOT EJECTED/NOT APPLICABLE</b>	GVWR:	
Drug Test Given:	<b>1 - NONE</b>	Occpnt Protect:	<b>03 - SHOULDER AND LAP BELT USED</b>	Cit Chrg Code 1:	
Total Occupants:	<b>1</b>	Source of Trans:	<b>01 - NOT TRANSPORTED</b>	Citation Charge 1:	
Vehicle Year:	<b>2005</b>	Died at Scene:	<b>01 - NOT APPLICABLE</b>	Cit Chrg Code 2:	
Vehicle Make:	<b>KENWORTH - KW</b>			Citation Charge 2:	
Vehicle Model:	<b>COM</b>			Citation Charge 3:	
Vehicle Style:	<b>TR</b>			Citation Charge 4:	
Vehicle Color:	<b>SILVER - SIL</b>				
Vehicle Config:	<b>07 - SINGLE-UNIT TRUCK (2-AXLE, 6-TIRE)</b>				
Vehicle Defect:	<b>01 - NONE</b>				
Vehicle Action:	<b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>				
Tow:	<b>1 - DRIVEN AWAY</b>				
Tow #:					
Initial Trvl Dir:	<b>04 - WEST</b>				
Vision Obscured:	<b>01 - NOT OBSCURED</b>				

**Unit 002**

Driver Name - Last: <b>FORD</b>	Bus Use:	Transported to: <b>N/A</b>
First: <b>CHARLES</b>		
Middle: <b>EDWARD</b>	Drvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by: <b>N/A</b>
City: <b>MOUNT AYR</b>		
State: <b>IA</b>	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>50854-0000</b>		
Suffix:	Point of Init Impact: <b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Male</b>	Most Damaged Area: <b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION</b>
Age: <b>66</b>	Undrrid/Ovrid: <b>1 - NONE</b>	
CDL: <b>YES</b>	Rpr/Rplc Cost: <b>\$1,000.00</b>	
License State: <b>IA</b>	Ext of Damage: <b>2 - MINOR DAMAGE</b>	
License Class: <b>A</b>	First Event: <b>09 - EQUIPMENT FAILURE (TIRES, BRAKES, ETC.)</b>	Carrier Name:
License Endorsmnt: <b>LX</b>	Second Event:	Carrier Address:
License Restrictions: <b>B</b>	Third Event:	Carrier City:
Speed Limit: <b>55</b>	Fourth Event:	Carrier State:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Most Harmful Event: <b>09 - EQUIPMENT FAILURE (TIRES, BRAKES, ETC.)</b>	Carrier Zip:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>	Abg Switch Stat: <b>03 - NOT DEPLOYED</b>	Cargo Body Type: <b>04 - CARGO TANK</b>
Alcohol Test Given: <b>NO</b>	Abg Deploy: <b>03 - NOT DEPLOYED</b>	Number of Axles:
Drug Test Given: <b>1 - NONE</b>	Trapped: <b>1 - NOT TRAPPED/APPLICABLE</b>	HazMat Involvement:
Total Occupants: <b>1</b>	Ejection: <b>1 - NOT APPLICABLE</b>	HazMat Placard:
Vehicle Year: <b>2016</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	Placard #:
Vehicle Make: <b>FREIGHTLINER - FRHT</b>	Occpnt Protect: <b>03 - SHOULDER AND LAP BELT USED</b>	HazMat Released?:
Vehicle Model:	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Converter Dolly:
Vehicle Style: <b>TR</b>	Died at Scene: <b>01 - NOT APPLICABLE</b>	GVWR:
Vehicle Color: <b>SILVER - SIL</b>		Cit Chrg Code 1:
Vehicle Config: <b>07 - SINGLE-UNIT TRUCK (2-AXLE, 6-TIRE)</b>		Citation Charge 1:
Vehicle Defect: <b>04 - BLOWOUT</b>		Cit Chrg Code 2:
Vehicle Action: <b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>		Citation Charge 2:
Tow: <b>1 - DRIVEN AWAY</b>		Citation Charge 3:
Tow #:		Citation Charge 4:
Initial Trvl Dir: <b>02 - EAST</b>		
Vision Obscured: <b>01 - NOT OBSCURED</b>		

**Accident Environment**

First Harmful Event Loc: <b>01 - ON ROADWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>5 - DARK, ROADWAY NOT LIGHTED</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	Type of Road Junc/Feat: <b>01 - NON-JUNCTION/NO SPECIAL FEATURE</b>
Surface Conditions: <b>01 - DRY</b>	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>30 - THROWN OR FALLING OBJECT</b>
Type:	
Workers Present:	

**Narrative**

UNIT 1 WAS TRAVELING WESTBOUND ON HWY 20, UNIT 2 WAS TRAVELING EASTBOUND ALSO ON HWY 20. UNIT 2 HAD A TIRE BLOW AND AS THE TIRE CAME OFF, UNIT 1 WAS DRIVING PAST AND MET UNIT 2 AS THE TIRE CAME OFF AND THE TIRE STRUCK UNIT 1 CAUSING DAMAGE TO UNIT 1

