

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **18-262**
 Date of Acc: **01/12/18**
 Time of Acc: **21:43** Hrs.
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**
 Officer: **EHLERS ALEX**
 Badge #: **47-10**
 Report Date: **01/12/2018**
 Officer Notified: **21:43** Hrs.
 Officer Arrived: **22:30** Hrs.
 Scene Investigated: **NO**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **IDA - 47**
 Acc Loc City: **HOLSTEIN - 3515**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00291075**
 Y-Coordinate: **04706203**
 Location Literal: **KASTNER DR**
 Description:

Unit 001

| | | |
|--|--|---|
| Driver Name - Last: JOHNSON | Bus Use: | Transported to: N/A |
| First: GLEN | | |
| Middle: HOWARD | Drvtr Distractions: 02 - NOT DISTRACTED | Transported by: N/A |
| City: HOLSTEIN | | |
| State: IA | Traffic Controls: 01 - NO CONTROLS PRESENT | Special Veh Func: 01 - NO SPECIAL FUNCTION |
| Zip: 51025-0000 | | |
| Suffix: | Point of Init Impact: 05 - REAR PASSENGER SIDE CORNER | Emergency Status: 01 - NOT APPLICABLE |
| Gender: Male | Most Damaged Area: 05 - REAR PASSENGER SIDE CORNER | Cont. Circum., Drvr: 98 - OTHER (EXPLAIN IN NARRATIVE) |
| Age: 79 | Undrdr/Ovrid: 1 - NONE | |
| CDL: NO | Rpr/Rplc Cost: \$1,500.00 | |
| License State: IA | Ext of Damage: 2 - MINOR DAMAGE | |
| License Class: C | First Event: 34 - RE-ENTERING ROADWAY | Carrier Name: |
| License Endorsmnt: | | Carrier Address: |
| License Restrictions: | Second Event: 35 - PARKED MOTOR VEHICLE | Carrier City: |
| Speed Limit: 25 | | Carrier State: |
| Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER | Third Event: | Carrier Zip: |
| Driver Condition: 01 - APPARENTLY NORMAL | Fourth Event: | Cargo Body Type: 01 - NOT APPLICABLE |
| Alcohol Test Given: NO | | Number of Axles: |
| Drug Test Given: 1 - NONE | Most Harmful Event: 35 - PARKED MOTOR VEHICLE | HazMat Involvement: |
| Total Occupants: 1 | Abg Switch Stat: | HazMat Placard: |
| Vehicle Year: 2007 | Abg Deploy: 01 - NOT APPLICABLE | Placard #: |
| Vehicle Make: CHRYSLER - CHRY | Trapped: 1 - NOT TRAPPED/APPLICABLE | HazMat Released?: |
| Vehicle Model: TNC | Ejection: 1 - NOT APPLICABLE | Converter Dolly: |
| Vehicle Style: VN | Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE | GVWR: |
| Vehicle Color: SILVER - SIL | Occpnt Protect: 01 - NOT APPLICABLE | Cit Chrg Code 1: |
| Vehicle Config: 04 - PASSENGER VAN (SEATS <9) | | Citation Charge 1: |
| Vehicle Defect: 01 - NONE | | Cit Chrg Code 2: |
| Vehicle Action: 09 - BACKING | | Citation Charge 2: |
| Tow: 1 - DRIVEN AWAY | | Citation Charge 3: |
| Tow #: | | Citation Charge 4: |
| Initial Trvl Dir: 02 - EAST | Source of Trans: 01 - NOT TRANSPORTED | |
| Vision Obscured: 01 - NOT OBSCURED | Died at Scene: 01 - NOT APPLICABLE | |

Unit 002

| | | |
|--|--|---|
| Driver Name - Last: | Bus Use: | Transported to: |
| First: | | |
| Middle: | Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER | Transported by: |
| City: | | |
| State: | Traffic Controls: 01 - NO CONTROLS PRESENT | Special Veh Func: 01 - NO SPECIAL FUNCTION |
| Zip: | | |
| Suffix: | Point of Init Impact: 11 - FRONT DRIVER SIDE CORNER | Emergency Status: 01 - NOT APPLICABLE |
| Gender: | | |
| Age: | Most Damaged Area: 11 - FRONT DRIVER SIDE CORNER | Cont. Circum., Drvr: 88 - NO IMPROPER ACTION |
| CDL: | Undridd/Ovrid: 1 - NONE | |
| License State: | Rpr/Rplc Cost: \$3,000.00 | |
| License Class: | Ext of Damage: 2 - MINOR DAMAGE | |
| License Endorsmnt: | First Event: 35 - PARKED MOTOR VEHICLE | |
| License Restrictions: | | Carrier Name: |
| Speed Limit: 25 | | Carrier Address: |
| Seating Position: | | Carrier City: |
| | Second Event: | Carrier State: |
| Driver Condition: 98 - OTHER (EXPLAIN IN NARR | | Carrier Zip: |
| Alcohol Test Given: | Third Event: | Cargo Body Type: 01 - NOT APPLICABLE |
| Drug Test Given: | | |
| Total Occupants: 0 | Fourth Event: | Number of Axles: |
| Vehicle Year: 2014 | | HazMat Involvement: |
| Vehicle Make: DODGE - DODG | | HazMat Placard: |
| Vehicle Model: DUR | | Placard #: |
| Vehicle Style: SW | Most Harmful Event: 35 - PARKED MOTOR VEHICLE | HazMat Released?: |
| Vehicle Color: RED - RED | | Converter Dolly: |
| Vehicle Config: 03 - SPORT UTILITY VEHICLE | Abg Switch Stat: | GVWR: |
| | Abg Deploy: | Cit Chrg Code 1: |
| Vehicle Defect: 01 - NONE | | Citation Charge 1: |
| Vehicle Action: 12 - LEGALLY PARKED | Trapped: | |
| | Ejection: | |
| Tow: 1 - DRIVEN AWAY | Ejection Path: | Cit Chrg Code 2: |
| | | Citation Charge 2: |
| Tow #: | Occpnt Protect: | |
| Initial Trvl Dir: 99 - UNKNOWN | | Citation Charge 3: |
| Vision Obscured: 01 - NOT OBSCURED | | |
| | Source of Trans: | Citation Charge 4: |
| | Died at Scene: | |

Accident Environment

| | |
|---|---|
| First Harmful Event Loc: 01 - ON ROADWAY | Roadway Characteristics |
| Manner of Crash/Collision: 98 - OTHER (EXPLAIN IN NARRATIVE) | Environment: 01 - NONE APPARENT |
| Light Conditions: 4 - DARK, ROADWAY LIGHTED | Roadway: 01 - NONE APPARENT |
| Weather Conditions: 01 - CLEAR | |
| | Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE |
| Surface Conditions: 01 - DRY | |
| | FRA No.: |
| Workzone Related: NO | Horizontal Alignment: |
| Activity: | Vertical Alignment: |
| Location: | |
| Type: | First Harmful Evt of Crash: 35 - PARKED MOTOR VEHICLE |
| Workers Present: | |

Narrative

unit 1 was backing out of its driveway. unit 1 struck unit 2 which was legally parked. unit 1 had made contact with unit 2 in the front driver's side causing damage. unit 1 had damage to its rear passenger side bumper.