

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-0362	Report to All Drivers:	At Intersection with:
Date of Acc: 01/18/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 18:52 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
Officer: TRUCKE COREY	Acc Loc City:	Distance 2:
Badge #: 47-6	Acc Dir From City:	Direction 2:
Report Date: 01/18/2018	Closest City:	X-Coordinate: 00283783
Officer Notified: 18:51 Hrs.	Miles From City:	Y-Coordinate: 04687371
Officer Arrived: 19:03 Hrs.	Road, Street, HWay:	Location Literal: BRADY AVE
Scene Investigated: YES	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: HOLMES	Bus Use:	Transported to:
First: LOIS		
Middle: ANN	Drvtr Distractions: 02 - NOT DISTRACTED	Transported by:
City: BATTLE CREEK		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51006-0000		
Suffix:	Point of Init 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Female	Impact:	
Age: 58	Most Damaged 12 - FRONT MIDDLE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
CDL: NO	Area:	
License State: IA	Undrrid/Ovrid: 1 - NONE	
License Class: C	Rpr/Rplc Cost: \$5,000.00	
License Endorsmnt: B	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Restrictions: B	First Event: 96 - OTHER NON-FIXED OBJECT (EXPLAIN IN NARRATIVE)	Carrier Name:
Speed Limit: 50		Carrier Address:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event:	Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier State:
Alcohol Test Given: NO	Third Event:	Carrier Zip:
Drug Test Given: 1 - NONE		Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 1	Fourth Event:	
Vehicle Year: 2010		Number of Axles:
Vehicle Make: CHEVROLET - CHEV	Most Harmful 96 - OTHER NON-FIXED OBJECT (EXPLAIN IN NARRATIVE)	HazMat Involvement:
Vehicle Model: IMP	Event:	HazMat Placard:
Vehicle Style: 4D	Abg Switch Stat:	Placard #:
Vehicle Color: SILVER - SIL	Abg Deploy: 03 - NOT DEPLOYED	HazMat Released?:
Vehicle Config: 01 - PASSENGER CAR		Converter Dolly:
Vehicle Defect: 01 - NONE	Trapped: 1 - NOT TRAPPED/APPLICABLE	GVWR:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Ejection: 2 - NOT EJECTED	Cit Chrg Code 1:
Tow: 1 - DRIVEN AWAY	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Citation Charge 1:
Tow #: 03 - SOUTH	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 2:
Initial Trvl Dir: 01 - NOT OBSCURED		Citation Charge 2:
Vision Obscured:	5 - UNINJURED	Citation Charge 3:
	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 04 - NON-MOTORIST ACTION
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 03 - DEBRIS
Weather Conditions: 01 - CLEAR	
Surface Conditions: 98 - OTHER (EXPLAIN IN NARRATIVE)	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Workzone Related: NO	FRA No.:
Activity:	Horizontal Alignment:
Location:	Vertical Alignment:
Type:	First Harmful Evt of Crash: 96 - OTHER NON-FIXED OBJECT (EXPLAIN IN NARRATIVE)
Workers Present:	

Non Motorist 001

Type: 98 - OTHER NON-MOTORIST (EXPLAIN IN NARRATIVE)	Location: 07 - NON-INTERSECTION: NOT WITHIN CROSSWALK
Name - Last: MEFFERD	Action: 98 - OTHER (EXPLAIN IN NARRATIVE)
First: KEVIN	Condition: 01 - APPARENTLY NORMAL
Middle: EUGENE	Safety Equipment: 04 - REFLECTIVE CLOTHING
Suffix:	Contributing Circumstances: 98 - OTHER (EXPLAIN IN NARRATIVE)
Address: 2729 BRADY AVE	
City: BATTLE CREEK	Alcohol Test Given: NO
State: IA	

Zip Code: **51006-0000**
Age: **59**
Sex: **MALE**
Unit No. of Vehicle Striking: **001**
Injury Status: **5 - UNINJURED**

Drug Test Given: **1 - NONE**
Source of Transport: **01 - NOT TRANSPORTED**
Died at Scene/Enroute: **01 - NOT APPLICABLE**
Transported to:
Transported by:

Narrative

Unit 1 was south bound on Brady Ave just south of 270th. The non-motorist (Kevin Mefferd) had cut a tree down which was on the roadway. It was dark. The driver of unit 1 could not see the tree down. Unit 1 struck the tree causing significant damage to her vehicle. The tree had been located on the property belonging to Kevin before being cut down. Kevin was wearing reflective clothing and attempted to get the driver to stop using a flashlight. No cones, flares, warning lights or other equipment was on the roadway. There was no damage to Kevin's property. Kevin's home insurance is State Farm Policy 15-CX-6976-3. Photos of the accident were taken.