

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **18-0618**
 Date of Acc: **01/29/18**
 Time of Acc: **08:00** Hrs.
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**
 Officer: **TRUCKE COREY**
 Badge #: **47-6**
 Report Date: **01/29/2018**
 Officer Notified: **12:15** Hrs.
 Officer Arrived: **12:33** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **YES**
 County: **IDA - 47**
 Acc Loc City: **HOLSTEIN - 3515**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00290898**
 Y-Coordinate: **04708695**
 Location Literal: **VT INDUSTRIES**
 Description:

Unit 001

| | | |
|--|---|---|
| Driver Name - Last: | Bus Use: | Transported to: |
| First: | | |
| Middle: | Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER | Transported by: |
| City: | Traffic Controls: 01 - NO CONTROLS PRESENT | Special Veh Func: |
| State: | | |
| Zip: | Point of Init 09 - MIDDLE DRIVER SIDE | Emergency Status: |
| Suffix: | Impact: | |
| Gender: | Most Damaged 09 - MIDDLE DRIVER SIDE | Cont. Circum., Drvr: 88 - NO IMPROPER ACTION |
| Age: | Area: | |
| CDL: | Undrrid/Ovrid: 1 - NONE | |
| License State: | Rpr/Rplc Cost: \$1,400.00 | |
| License Class: | Ext of Damage: 2 - MINOR DAMAGE | |
| License Endorsmnt: | First Event: | Carrier Name: |
| License Restrictions: | | Carrier Address: |
| Speed Limit: 25 | Second Event: | Carrier City: |
| Seating Position: | | Carrier State: |
| | Third Event: | Carrier Zip: |
| Driver Condition: | | Cargo Body Type: 01 - NOT APPLICABLE |
| Alcohol Test Given: | Fourth Event: | Number of Axles: |
| Drug Test Given: | | HazMat Involvement: |
| Total Occupants: 0 | Most Harmful Event: | HazMat Placard: |
| Vehicle Year: 2014 | Abg Switch Stat: | Placard #: |
| Vehicle Make: FORD - FORD | Abg Deploy: | HazMat Released?: |
| Vehicle Model: FUS | Trapped: | Converter Dolly: |
| Vehicle Style: 4D | Ejection: | GVWR: |
| Vehicle Color: SILVER - SIL | Ejection Path: | Cit Chrg Code 1: |
| Vehicle Config: 01 - PASSENGER CAR | Occpnt Protect: | Citation Charge 1: |
| Vehicle Defect: 01 - NONE | | |
| Vehicle Action: 12 - LEGALLY PARKED | Source of Trans: | Citation Charge 2: |
| Tow: 1 - DRIVEN AWAY | Died at Scene: | Citation Charge 3: |
| Tow #: | | Citation Charge 4: |
| Initial Trvl Dir: 99 - UNKNOWN | | |
| Vision Obscured: | | |

Unit 002

| | | |
|--|---|----------------------|
| Driver Name - Last: | Bus Use: | Transported to: |
| First: | | |
| Middle: | Drvr Distractions: | Transported by: |
| City: | | |
| State: | Traffic Controls: | Special Veh Func: |
| Zip: | | |
| Suffix: | Point of Init | Emergency Status: |
| Gender: | Impact: | |
| Age: | Most Damaged | Cont. Circum., Drvr: |
| CDL: | Area: | |
| License State: | Undrrid/Ovrid: | |
| License Class: | Rpr/Rplc Cost: | |
| License Endorsmnt: | Ext of Damage: | |
| License Restrictions: | First Event: 35 - PARKED MOTOR VEHICLE | Carrier Name: |
| Speed Limit: | | Carrier Address: |
| Seating Position: | | Carrier City: |
| | Second Event: 72 - HIT AND RUN | Carrier State: |
| Driver Condition: | | Carrier Zip: |
| Alcohol Test Given: | Third Event: | Cargo Body Type: |
| Drug Test Given: | | |
| Total Occupants: 1 | Fourth Event: | Number of Axles: |
| Vehicle Year: | | HazMat Involvement: |
| Vehicle Make: | | HazMat Placard: |
| Vehicle Model: | Most Harmful | Placard #: |
| Vehicle Style: | Event: | HazMat Released?: |
| Vehicle Color: | Abg Switch Stat: | Converter Dolly: |
| Vehicle Config: | Abg Deploy: | GVWR: |
| Vehicle Defect: | | Cit Chrg Code 1: |
| | Trapped: | Citation Charge 1: |
| Vehicle Action: 18 - ENTERING A PARKED POSITION | Ejection: | |
| | Ejection Path: | Cit Chrg Code 2: |
| Tow: | | Citation Charge 2: |
| | Occpnt Protect: | |
| Tow #: | | |
| Initial Trvl Dir: 99 - UNKNOWN | Source of Trans: | Citation Charge 3: |
| Vision Obscured: | Died at Scene: | Citation Charge 4: |

Accident Environment

| | |
|---|---|
| First Harmful Event Loc: 07 - IN PARKING LANE/ZONE | Roadway Characteristics |
| Manner of Crash/Collision: 98 - OTHER (EXPLAIN IN NARRATIVE) | Environment: 01 - NONE APPARENT |
| Light Conditions: 9 - UNKNOWN | Roadway: 01 - NONE APPARENT |
| Weather Conditions: 01 - CLEAR | |
| | Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE |
| Surface Conditions: 01 - DRY | |
| | FRA No.: |
| Workzone Related: NO | Horizontal Alignment: |
| Activity: | Vertical Alignment: |
| Location: | |
| Type: | First Harmful Evt of Crash: 35 - PARKED MOTOR VEHICLE |
| Workers Present: | |

Narrative

Unit 1 was legally parked in the parking lot on the north side of VT industries. Unit 1 was struck by an unknown second vehicle causing minor damage. No current suspect vehicles are available.