

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **18-00860**
 Date of Acc: **02/09/18**
 Time of Acc: **16:02** Hrs.
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**
 Officer: **STEHR MICHAEL**
 Badge #: **47-3**
 Report Date: **02/09/2018**
 Officer Notified: **15:56** Hrs.
 Officer Arrived: **15:57** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **IDA - 47**
 Acc Loc City: **IDA GROVE - 3650**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00296386**
 Y-Coordinate: **04691052**
 Location Literal: **2ND ST**
 Description:

Unit 001

Driver Name - Last: **EUCHNER**
 First: **VERNICE**
 Middle: **JEAN**
 City: **IDA GROVE**
 State: **IA**
 Zip: **51445-0000**
 Suffix:
 Gender: **Female**
 Age: **70**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt: **B**
 License Restrictions: **B**
 Speed Limit: **25**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2001**
 Vehicle Make: **BUICK - BUIC**
 Vehicle Model: **LES**
 Vehicle Style: **4D**
 Vehicle Color: **MAROON, BURGUNDY (PURPL**
 Vehicle Config: **01 - PASSENGER CAR**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **02 - TURNING LEFT**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **04 - WEST**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **04 - REAR PASSENGER SIDE**
 Most Damaged Area: **04 - REAR PASSENGER SIDE**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$5,000.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **33 - VEHICLE IN TRAFFIC**
 Second Event:
 Third Event:
 Fourth Event:
 Most Harmful Event: **33 - VEHICLE IN TRAFFIC**
 Abg Switch Stat:
 Abg Deploy: **01 - NOT APPLICABLE**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **1 - NOT APPLICABLE**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to: **N/A**
 Transported by: **N/A**
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **42 - FTYROW: MAKING LEFT TURN**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:		
State:	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip:		
Suffix:	Point of Init Impact: 05 - REAR PASSENGER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender:		
Age:	Most Damaged Area: 05 - REAR PASSENGER SIDE CORNER	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
CDL:	Undrrid/Ovrid: 1 - NONE	
License State:	Rpr/Rplc Cost: \$2,000.00	
License Class:	Ext of Damage: 2 - MINOR DAMAGE	
License Endorsmnt:	First Event: 35 - PARKED MOTOR VEHICLE	
License Restrictions:		Carrier Name:
Speed Limit: 25		Carrier Address:
Seating Position:	Second Event:	Carrier City:
		Carrier State:
Driver Condition:	Third Event:	Carrier Zip:
Alcohol Test Given:		Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given:	Fourth Event:	
Total Occupants:		Number of Axles:
Vehicle Year: 2013	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	HazMat Involvement:
Vehicle Make: DODGE - DODG		HazMat Placard:
Vehicle Model: DUR	Abg Switch Stat:	Placard #:
Vehicle Style: SW	Abg Deploy:	HazMat Released?:
Vehicle Color: RED - RED		Converter Dolly:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Trapped:	GVWR:
	Ejection:	Cit Chrg Code 1:
Vehicle Defect: 01 - NONE	Ejection Path:	Citation Charge 1:
	Occpnt Protect:	
Vehicle Action: 12 - LEGALLY PARKED		Cit Chrg Code 2:
		Citation Charge 2:
Tow: 1 - DRIVEN AWAY		
		Citation Charge 3:
Tow #:	Source of Trans:	
Initial Trvl Dir:	Died at Scene:	Citation Charge 4:
Vision Obscured:		

Unit 003

Driver Name - Last: WILTSE	Bus Use:	Transported to: N/A
First: KENNETH		
Middle: JAMES	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: N/A
City: IDA GROVE		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51445-0000		
Suffix:	Point of Init Impact: 12 - FRONT MIDDLE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 12 - FRONT MIDDLE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Age: 47	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$1,500.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: C	First Event: 33 - VEHICLE IN TRAFFIC	
License Endorsmnt:		
License Restrictions:	Second Event:	Carrier Name:
Speed Limit: 25		Carrier Address:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier State:
Alcohol Test Given: NO	Fourth Event:	Carrier Zip:
Drug Test Given: 1 - NONE		Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 1		
Vehicle Year: 1993	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Number of Axles:
Vehicle Make: CHEVROLET - CHEV		HazMat Involvement:
Vehicle Model: C15	Abg Switch Stat:	HazMat Placard:
Vehicle Style: PK	Abg Deploy: 03 - NOT DEPLOYED	Placard #:
Vehicle Color: GREEN - GRN		HazMat Released?:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:
Vehicle Defect: 01 - NONE	Ejection: 1 - NOT APPLICABLE	GVWR:
	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 1:
Tow: 1 - DRIVEN AWAY		Cit Chrg Code 2:
		Citation Charge 2:
Tow #:		
Initial Trvl Dir: 02 - EAST	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 98 - OTHER (EXPLAIN IN NARRATIVE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 04 - SNOW	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

UNIT 1 WAS TRAVELING WEST BOUND ON 2ND STREET, AND MADE AN ILLEGAL LEFT TURN ACROSS TRAFFIC AND ATTEMPTED TO ENTER A PARKING SPOT, BUT DID NOT YIELD TO UNIT 3 AND UNIT 3 DID STRIKE UNIT 1. UNIT 3 WAS EAST BOUND ON 2ND STREET AND DUE TO A SNOW COVERED STREET COULD NOT STOP IN TIME WHEN UNIT 1 TURNED IN FRONT OF IT AND HIT UNIT 1. UNIT 3 PUSHED UNIT 1 INTO UNIT 2 WHICH WAS LEGALLY PARKED.

Diagram



2ND STREET

