

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **18-1728**
 Date of Acc: **03/17/18**
 Time of Acc: **11:54** Hrs.
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**
 Officer: **VAN EGDOM BRADY**
 Badge #: **47-5**
 Report Date: **03/17/2018**
 Officer Notified: **11:54** Hrs.
 Officer Arrived: **11:56** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **YES**
 County: **IDA - 47**
 Acc Loc City: **IDA GROVE - 3650**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00296687**
 Y-Coordinate: **04691449**
 Location Literal: **MOOREHEAD AVE**
 Description:

Unit 001

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Dvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
State:	Point of Init Impact: 11 - FRONT DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Zip:	Most Damaged Area: 11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Dvr: 88 - NO IMPROPER ACTION
Suffix:	Undrrid/Ovrid: 1 - NONE	
Gender:	Rpr/Rplc Cost: \$1,200.00	Carrier Name:
Age:	Ext of Damage: 2 - MINOR DAMAGE	Carrier Address:
CDL:	First Event: 35 - PARKED MOTOR VEHICLE	Carrier City:
License State:	Second Event: 33 - VEHICLE IN TRAFFIC	Carrier State:
License Class:	Third Event:	Carrier Zip:
License Endorsmnt:	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions:	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Number of Axles:
Speed Limit:	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
Driver Condition:	Trapped:	Placard #:
Alcohol Test Given:	Ejection:	HazMat Released?:
Drug Test Given:	Ejection Path:	Converter Dolly:
Total Occupants: 0	Occpnt Protect:	GVWR:
Vehicle Year: 2010	Source of Trans:	Cit Chrg Code 1:
Vehicle Make: GENERAL MOTORS - GMC	Died at Scene:	Citation Charge 1:
Vehicle Model: YUK		Cit Chrg Code 2:
Vehicle Style: SW		Citation Charge 2:
Vehicle Color: SILVER - SIL		Citation Charge 3:
Vehicle Config: 03 - SPORT UTILITY VEHICLE		Citation Charge 4:
Vehicle Defect: 01 - NONE		
Vehicle Action: 12 - LEGALLY PARKED		
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir:		
Vision Obscured:		

Unit 002

Driver Name - Last: MURPHREE	Bus Use:	Transported to:
First: ALYSSA		
Middle: LYNN	Drvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: ARTHUR		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51431		
Suffix:	Point of Init Impact: 07 - REAR DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Female	Most Damaged Area: 07 - REAR DRIVER SIDE CORNER	Cont. Circum., Drvr: 19 - STARTING OR BACKING IMPROPERLY
Age: 23	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$100.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: 0	First Event: 33 - VEHICLE IN TRAFFIC	
License Endorsmnt:		Carrier Name:
License Restrictions:		Carrier Address:
Speed Limit:		Carrier City:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event: 35 - PARKED MOTOR VEHICLE	Carrier State:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier Zip:
Alcohol Test Given: NO	Third Event:	Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given: 1 - NONE		
Total Occupants: 1	Fourth Event:	Number of Axles:
Vehicle Year: 2003		HazMat Involvement:
Vehicle Make: TOYO		HazMat Placard:
Vehicle Model: COROLLA CE/LE/S	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	Placard #:
Vehicle Style: 4D		HazMat Released?:
Vehicle Color: GRAY - GRY	Abg Switch Stat:	Converter Dolly:
Vehicle Config: 01 - PASSENGER CAR	Abg Deploy: 03 - NOT DEPLOYED	GVWR:
Vehicle Defect: 01 - NONE		Cit Chrg Code 1: 321.218(1)
	Trapped: 1 - NOT TRAPPED/APPLICABLE	Citation Charge 1: DRIVING WHILE LICENSE UNDER SUSPENSION
Vehicle Action: 09 - BACKING	Ejection: 1 - NOT APPLICABLE	
	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Tow: 1 - DRIVEN AWAY	Occpnt Protect: 99 - UNKNOWN	Citation Charge 2:
Tow #:		
Initial Trvl Dir: 02 - EAST		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED	5 - UNINJURED	
	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Property Damage 001

Object Damaged: NO PASSING ZONE SIGN	Company Owner Name:
Estimate of Damage: \$250.00	City:
Owner's Name - Last:	State:
First:	Zip Code:
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 98 - OTHER (EXPLAIN IN NARRATIVE)	Roadway Characteristics
Manner of Crash/Collision: 98 - OTHER (EXPLAIN IN NARRATIVE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 02 - WET	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 35 - PARKED MOTOR VEHICLE
Type:	
Workers Present:	

Narrative

UNIT 1 WAS LEGALLY PARKED IN THE PARKING LOT OF DOLLAR GENERAL, FACING WEST. UNIT 2 WAS ALSO LEGALLY PARKED IN THE PARKING LOT, FACING WEST. UNIT 2 THEN BACKED OUT OF THE PARKING SPOT WHICH WAS IN FRONT OF UNIT 1. UNIT 2 FAILED TO SEE UNIT 1 AND BACKED INTO UNIT 1, CAUSING DAMAGE TO THE FRONT DRIVERS SIDE BUMPER OF UNIT 1. UNIT 2 SUSTAINED MINOR DAMAGE TO THE REAR DRIVERS SIDE BUMPER.

Diagram

