

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number:	<b>18-1880</b>	Report to All Drivers:		At Intersection with:	
Date of Acc:	<b>03/23/18</b>	Legal Intervention:	<b>NO</b>	Div HWay Trvl Dir:	
Time of Acc:	<b>16:00</b> Hrs.	Private Property:	<b>NO</b>	Distance 1:	
Name of Agency:	<b>IDA COUNTY SHERIFF'S OFFICE</b>	County:	<b>IDA - 47</b>	Direction 1:	
Officer:	<b>STEHR MICHAEL</b>	Acc Loc City:	<b>IDA GROVE - 3650</b>	Distance 2:	
Badge #:	<b>47-3</b>	Acc Dir From City:		Direction 2:	
Report Date:	<b>03/23/2018</b>	Closest City:		X-Coordinate:	<b>00296416</b>
Officer Notified:	<b>18:15</b> Hrs.	Miles From City:		Y-Coordinate:	<b>04691703</b>
Officer Arrived:	<b>18:24</b> Hrs.	Road, Street, HWay:		Location Literal:	<b>OAK GROVE DR</b>
Scene Investigated:	<b>NO</b>	Definable Location:		Description:	
		Milepost Number:			

**Unit 001**

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: <b>01 - NOT APPLICABLE/NO DRIVER</b>	Transported by:
City:		
State:	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip:		
Suffix:	Point of Init Impact: <b>02 - FRONT PASSENGER SIDE</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender:	Most Damaged Area: <b>02 - FRONT PASSENGER SIDE</b>	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION</b>
Age:	Undrrid/Ovrid: <b>1 - NONE</b>	
CDL:	Rpr/Rplc Cost: <b>\$1,500.00</b>	
License State:	Ext of Damage: <b>2 - MINOR DAMAGE</b>	
License Class:	First Event: <b>35 - PARKED MOTOR VEHICLE</b>	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions:	Second Event: <b>72 - HIT AND RUN</b>	Carrier City:
Speed Limit:		Carrier State:
Seating Position:	Third Event:	Carrier Zip:
		Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Driver Condition:	Fourth Event:	Number of Axles:
Alcohol Test Given:		HazMat Involvement:
Drug Test Given:	Most Harmful Event: <b>35 - PARKED MOTOR VEHICLE</b>	HazMat Placard:
Total Occupants:	Abg Switch Stat:	Placard #:
Vehicle Year: <b>2014</b>	Abg Deploy:	HazMat Released?:
Vehicle Make: <b>HYUNDAI - HYUN</b>	Trapped:	Converter Dolly:
Vehicle Model: <b>SFE</b>	Ejection:	GVWR:
Vehicle Style: <b>SW</b>	Ejection Path:	Cit Chrg Code 1:
Vehicle Color: <b>WHITE - WHI</b>	Occpnt Protect:	Citation Charge 1:
Vehicle Config: <b>03 - SPORT UTILITY VEHICLE</b>		
Vehicle Defect: <b>01 - NONE</b>	Source of Trans:	Citation Charge 2:
Vehicle Action: <b>12 - LEGALLY PARKED</b>	Died at Scene:	Citation Charge 3:
Tow: <b>1 - DRIVEN AWAY</b>		Citation Charge 4:
Tow #:		
Initial Trvl Dir:		
Vision Obscured:		

**Unit 002**

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: <b>99 - UNKNOWN</b>	Transported by:
City:		
State:	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip:		
Suffix:	Point of Init Impact: <b>99 - UNKNOWN</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender:		
Age:	Most Damaged Area: <b>99 - UNKNOWN</b>	Cont. Circum., Drvr: <b>99 - UNKNOWN</b>
CDL:	Undrrid/Ovrid: <b>9 - UNKNOWN</b>	
License State:	Rpr/Rplc Cost: <b>9 - UNKNOWN</b>	
License Class:	Ext of Damage: <b>9 - UNKNOWN</b>	
License Endorsmnt:	First Event: <b>35 - PARKED MOTOR VEHICLE</b>	Carrier Name:
License Restrictions:		Carrier Address:
Speed Limit:		Carrier City:
Seating Position:		Carrier State:
	Second Event: <b>72 - HIT AND RUN</b>	Carrier Zip:
Driver Condition: <b>99 - UNKNOWN</b>		Cargo Body Type: <b>99 - UNKNOWN</b>
Alcohol Test Given:	Third Event:	
Drug Test Given:		Number of Axles:
Total Occupants:	Fourth Event:	HazMat Involvement:
Vehicle Year:		HazMat Placard:
Vehicle Make:		Placard #:
Vehicle Model:	Most Harmful Event: <b>35 - PARKED MOTOR VEHICLE</b>	HazMat Released?:
Vehicle Style:		Converter Dolly:
Vehicle Color:	Abg Switch Stat:	GVWR:
Vehicle Config: <b>99 - UNKNOWN</b>	Abg Deploy:	Cit Chrg Code 1:
Vehicle Defect: <b>99 - UNKNOWN</b>		Citation Charge 1:
Vehicle Action: <b>99 - UNKNOWN</b>	Trapped:	
	Ejection:	Cit Chrg Code 2:
Tow:	Ejection Path:	Citation Charge 2:
	Occpnt Protect:	
Tow #:		Citation Charge 3:
Initial Trvl Dir:	Source of Trans:	
Vision Obscured: <b>99 - UNKNOWN</b>	Died at Scene:	Citation Charge 4:

**Accident Environment**

First Harmful Event Loc: <b>07 - IN PARKING LANE/ZONE</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>99 - UNKNOWN</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	
	Type of Road Junc/Feat: <b>01 - NON-JUNCTION/NO SPECIAL FEATURE</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: <b>35 - PARKED MOTOR VEHICLE</b>
Workers Present:	

**Narrative**

Unit 1 was sitting legally parked at Shopko in Ida Grove. An unknown vehicle hit unit 1 on the passenger side front causing damage to the front quarter panel to the vehicle. Suspect vehicle is still at large