

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-2000	Report to All Drivers:	At Intersection with:
Date of Acc: 03/28/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 05:50 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
	Acc Loc City: IDA GROVE - 3650	Distance 2:
Officer: ANDERSON FRED	Acc Dir From City:	Direction 2:
	Closest City:	X-Coordinate: 00297012
Badge #: 47-2	Miles From City:	Y-Coordinate: 04691601
Report Date: 03/28/2018	Road, Street, HWay:	Location Literal: WASHINGTON ST
Officer Notified: 06:02 Hrs.	Definable Location:	Description:
Officer Arrived: 06:15 Hrs.	Milepost Number:	
Scene Investigated: YES		

Unit 001

Driver Name - Last: REIS	Bus Use:	Transported to: NONE
First: KARY		
Middle: JON	Dvr Distractions: 02 - NOT DISTRACTED	Transported by: NONE
City: IDA GROVE		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51445-0000		
Suffix:	Point of Init Impact: 11 - FRONT DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 11 - FRONT DRIVER SIDE CORNER	Cont. Circum., Dvr: 50 - VISION OBSTRUCTED
Age: 46	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$1,000.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: C	First Event: 03 - RAN OFF ROAD, LEFT	Carrier Name:
License Endorsmnt: S		Carrier Address:
License Restrictions: S	Second Event: 47 - CULVERT/PIPE OPENING	Carrier City:
Speed Limit: 25		Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event: 54 - UTILITY POLE/LIGHT SUPPORT	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO		Number of Axles:
Drug Test Given: 1 - NONE	Most Harmful Event: 47 - CULVERT/PIPE OPENING	HazMat Involvement:
Total Occupants: 1	Abg Switch Stat: 03 - NOT DEPLOYED	HazMat Placard:
Vehicle Year: 2003	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Vehicle Make: MERCURY - MERC	Ejection: 2 - NOT EJECTED	HazMat Released?:
Vehicle Model: SAB	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Vehicle Style: 4D	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	GVWR:
Vehicle Color: WHITE - WHI	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Config: 01 - PASSENGER CAR	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Defect: 01 - NONE		Cit Chrg Code 2:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		Citation Charge 2:
Tow: 1 - DRIVEN AWAY		Citation Charge 3:
Tow #: 03 - SOUTH		Citation Charge 4:
Initial Trvl Dir: 12 - FROSTED WINDOWS/WINDSHIELD		

Property Damage 001

Object Damaged: UTILITY POLE SUPPORT	Company Owner Name: MIDAMERICAN ENERGY
Estimate of Damage: \$100.00	City: IDA GROVE
Owner's Name - Last:	State: IA
First:	Zip Code: 51445
Middle:	
Suffix:	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 03 - VISUAL OBSTRUCTION
Light Conditions: 4 - DARK, ROADWAY LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
Surface Conditions: 01 - DRY	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 57 - OTHER POST/POLE/SUPPORT (EXPLAIN IN NARRATIVE)
Type:	
Workers Present:	

Narrative

Unit #1 was south bound on Washington Street and at the intersection of Iowa Street. Due to frosted a frosted windshield, the drive drove off the road to the left and struck a culvert and sidewalk, The car continued to hit a supporting wire to a utility pole.

Diagram

