

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-2680	Report to All Drivers:	At Intersection with:
Date of Acc: 04/22/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 11:46 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
	Acc Loc City: IDA GROVE - 3650	Distance 2:
Officer: ANDERSON FRED	Acc Dir From City:	Direction 2:
	Closest City:	X-Coordinate: 00296384
Badge #: 47-2	Miles From City:	Y-Coordinate: 04691545
Report Date: 04/22/2018	Road, Street, HWay:	Location Literal: OAK GROVE DR AND ASH DR
Officer Notified: 11:46 Hrs.	Definable Location:	Description:
Officer Arrived: 11:48 Hrs.	Milepost Number:	
Scene Investigated: YES		

Unit 001

Driver Name - Last: MORROW	Bus Use:	Transported to: NONE
First: CHAD		
Middle: ALLAN	Dvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: CUSHING		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51018-0000		
Suffix:	Point of Init Impact: 03 - MIDDLE PASSENGER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 03 - MIDDLE PASSENGER SIDE	Cont. Circum., Dvr: 06 - LOST CONTROL
Age: 45	Undrrid/Ovrid: 1 - NONE	
CDL:	Rpr/Rplc Cost: \$1,000.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: A	First Event: 11 - LOSS OF TRACTION	Carrier Name:
License Endorsmnt: LNT		Carrier Address:
License Restrictions:	Second Event: 06 - EVASIVE ACTION (SWERVE, PANIC BRAKING, AVOIDANCE)	Carrier City:
Speed Limit: 25		Carrier State:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event: 20 - OVERTURN/ROLLOVER	Carrier Zip:
Driver Condition: 01 - APPARENTLY NORMAL		Cargo Body Type: 01 - NOT APPLICABLE
Alcohol Test Given: NO	Fourth Event:	
Drug Test Given: 1 - NONE	Most Harmful Event: 20 - OVERTURN/ROLLOVER	Number of Axles:
Total Occupants: 1	Abg Switch Stat:	HazMat Involvement:
Vehicle Year: 2007	Abg Deploy: 01 - NOT APPLICABLE	HazMat Placard:
Vehicle Make: HARLEY DAVIDSON - HD		Placard #:
Vehicle Model: FHT	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Released?:
Vehicle Style: MC	Ejection: 4 - TOTALLY EJECTED	Converter Dolly:
Vehicle Color: BLUE - BLU	Ejection Path: 98 - OTHER (EXPLAIN IN NARRATIVE)	GVWR:
Vehicle Config: 17 - MOTORCYCLE	Occpnt Protect: 01 - NOT APPLICABLE	Cit Chrg Code 1:
Vehicle Defect: 01 - NONE		Citation Charge 1:
Vehicle Action: 02 - TURNING LEFT	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 2:
Tow: 1 - DRIVEN AWAY	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 2:
Tow #:		Citation Charge 3:
Initial Trvl Dir: 03 - SOUTH		Citation Charge 4:
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 08 - SAND	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 98 - OTHER (EXPLAIN IN NARRATIVE)
Type:	
Workers Present:	

Narrative

Unit #1 was south bound on Susan Lawrence Drive. Unit #1 lost control due to sand on the roadway. Unit #1 entered into a skid and the driver was ejected from the bike causing minor injuries.

