

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

| | | |
|--|-------------------------------|--|
| Case Number: 18-2936 | Report to All Drivers: | At Intersection with: |
| Date of Acc: 04/30/18 | Legal Intervention: NO | Div HWay Trvl Dir: |
| Time of Acc: 20:48 Hrs. | Private Property: NO | Distance 1: |
| Name of Agency: IDA COUNTY SHERIFF'S OFFICE | County: IDA - 47 | Direction 1: |
| Officer: VAN WYHE KOREY | Acc Loc City: | Distance 2: |
| Badge #: 47-9 | Acc Dir From City: | Direction 2: |
| Report Date: 04/30/2018 | Closest City: | X-Coordinate: 00294990 |
| Officer Notified: 20:50 Hrs. | Miles From City: | Y-Coordinate: 04697113 |
| Officer Arrived: 21:08 Hrs. | Road, Street, HWay: | Location Literal: D037/210TH ST |
| Scene Investigated: YES | Definable Location: | Description: |
| | Milepost Number: | |

Unit 001

| | | |
|--|---|---|
| Driver Name - Last: WUNSCHHEL | Bus Use: | Transported to: N/A |
| First: KELBY | Dvrv Distractions: 02 - NOT DISTRACTED | Transported by: N/A |
| Middle: EDWARD | Traffic Controls: 01 - NO CONTROLS PRESENT | Special Veh Func: 01 - NO SPECIAL FUNCTION |
| City: HOLSTEIN | Point of Init Impact: 12 - FRONT MIDDLE | Emergency Status: 01 - NOT APPLICABLE |
| State: IA | Most Damaged Area: 11 - FRONT DRIVER SIDE CORNER | Cont. Circum., Dvrv: 98 - OTHER (EXPLAIN IN NARRATIVE) |
| Zip: 51025 | Undridd/Ovrid: 1 - NONE | Carrier Name: |
| Suffix: | Rpr/Rplc Cost: \$5,500.00 | Carrier Address: |
| Gender: Male | Ext of Damage: 3 - FUNCTIONAL DAMAGE | Carrier City: |
| Age: 21 | First Event: 31 - ANIMAL | Carrier State: |
| CDL: NO | Second Event: | Carrier Zip: |
| License State: IA | Third Event: | Cargo Body Type: 01 - NOT APPLICABLE |
| License Class: C | Fourth Event: | Number of Axles: |
| License Endorsmnt: | Most Harmful Event: 31 - ANIMAL | HazMat Involvement: |
| License Restrictions: | Abg Switch Stat: | HazMat Placard: |
| Speed Limit: 45 | Abg Deploy: 01 - NOT APPLICABLE | Placard #: |
| Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER | Trapped: 1 - NOT TRAPPED/APPLICABLE | HazMat Released?: |
| Driver Condition: 01 - APPARENTLY NORMAL | Ejection: 1 - NOT APPLICABLE | Converter Dolly: |
| Alcohol Test Given: NO | Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE | GVWR: |
| Drug Test Given: 1 - NONE | Occpnt Protect: 03 - SHOULDER AND LAP BELT USED | Cit Chrg Code 1: |
| Total Occupants: 1 | Source of Trans: 01 - NOT TRANSPORTED | Citation Charge 1: |
| Vehicle Year: 2012 | Died at Scene: 01 - NOT APPLICABLE | Cit Chrg Code 2: |
| Vehicle Make: GENERAL MOTORS - GMC | | Citation Charge 2: |
| Vehicle Model: SIERRA K1500 SL | | Citation Charge 3: |
| Vehicle Style: PK | | Citation Charge 4: |
| Vehicle Color: BLACK - BLK | | |
| Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP) | | |
| Vehicle Defect: 01 - NONE | | |
| Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT | | |
| Tow: 1 - DRIVEN AWAY | | |
| Tow #: | | |
| Initial Trvl Dir: 02 - EAST | | |
| Vision Obscured: 01 - NOT OBSCURED | | |

Accident Environment

| | |
|---|---|
| First Harmful Event Loc: 01 - ON ROADWAY | Roadway Characteristics |
| Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE) | Environment: 01 - NONE APPARENT |
| Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED | Roadway: 01 - NONE APPARENT |
| Weather Conditions: 01 - CLEAR | Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE |
| Surface Conditions: 10 - GRAVEL | FRA No.: |
| Workzone Related: NO | Horizontal Alignment: |
| Activity: | Vertical Alignment: |
| Location: | First Harmful Evt of Crash: 31 - ANIMAL |
| Type: | |
| Workers Present: | |

Narrative

Unit 1 was traveling eastbound on 210th near Indian Ave in rural Ida County. A deer entered the roadway from the south ditch, causing unit 1 to strike the deer. Unit 1 sustained functional damage and was driven away from the scene. No injuries were reported in this accident.

