

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: <b>18-3118</b>	Report to All Drivers:	At Intersection with:
Date of Acc: <b>05/07/18</b>	Legal Intervention: <b>NO</b>	Div HWay Trvl Dir:
Time of Acc: <b>20:45</b> Hrs.	Private Property: <b>NO</b>	Distance 1:
Name of Agency: <b>IDA COUNTY SHERIFF'S OFFICE</b>	County: <b>IDA - 47</b>	Direction 1:
Officer: <b>TRUCKE COREY</b>	Acc Loc City:	Distance 2:
Badge #: <b>47-6</b>	Acc Dir From City:	Direction 2:
Report Date: <b>05/07/2018</b>	Closest City:	X-Coordinate: <b>00289520</b>
Officer Notified: <b>21:01</b> Hrs.	Miles From City:	Y-Coordinate: <b>04690078</b>
Officer Arrived: <b>21:01</b> Hrs.	Road, Street, HWay:	Location Literal: <b>STATE 175/IOWA 175 AND FAITH</b>
Scene Investigated: <b>NO</b>	Definable Location:	Description: <b>AVE</b>
	Milepost Number:	

**Unit 001**

Driver Name - Last: <b>MILLER</b>	Bus Use:	Transported to:
First: <b>DARYL</b>		
Middle: <b>ALAN</b>	Drvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City: <b>BATTLE CREEK</b>	Traffic Controls:	Special Veh Func:
State: <b>IA</b>	Point of Init Impact:	Emergency Status:
Zip: <b>51006</b>	Most Damaged Area:	Cont. Circum., Drvr: <b>88 - NO IMPROPER ACTION</b>
Suffix:	Undrrid/Ovrid:	
Gender: <b>Male</b>	Rpr/Rplc Cost: <b>\$2,500.00</b>	Carrier Name:
Age: <b>71</b>	Ext of Damage:	Carrier Address:
CDL: <b>YES</b>	First Event:	Carrier City:
License State: <b>IA</b>	Second Event:	Carrier State:
License Class: <b>A</b>	Third Event:	Carrier Zip:
License Endorsmnt:	Fourth Event:	Cargo Body Type: <b>01 - NOT APPLICABLE</b>
License Restrictions:	Most Harmful Event:	Number of Axles:
Speed Limit:	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
Driver Condition:	Trapped:	Placard #:
Alcohol Test Given: <b>NO</b>	Ejection:	HazMat Released?:
Drug Test Given: <b>1 - NONE</b>	Ejection Path:	Converter Dolly:
Total Occupants: <b>1</b>	Occpnt Protect:	GVWR:
Vehicle Year: <b>2017</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Cit Chrg Code 1:
Vehicle Make: <b>HYUNDAI - HYUN</b>	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 1:
Vehicle Model: <b>IONIQ BLUE</b>		Citation Charge 2:
Vehicle Style: <b>PC</b>		Citation Charge 3:
Vehicle Color: <b>BLACK - BLK</b>		Citation Charge 4:
Vehicle Config: <b>01 - PASSENGER CAR</b>		
Vehicle Defect:		
Vehicle Action:		
Tow: <b>1 - DRIVEN AWAY</b>		
Tow #:		
Initial Trvl Dir:		
Vision Obscured:		

**Accident Environment**

First Harmful Event Loc:	<b>Roadway Characteristics</b>
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>31 - ANIMAL</b>
Type:	
Workers Present:	

**Narrative**

Unit 1 was headed west bound on Highway 175 near Faith Ave in Ida County IA when a deer crossed the road. Unit 1 struck the deer causing functional damage. Unit 1 was able to be driven from the scene. See above for damage estimates