

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-3614	Report to All Drivers:	At Intersection with:
Date of Acc: 05/26/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 20:46 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
	Acc Loc City: GALVA - 2805	Distance 2:
Officer: MCMILLEN ROB	Acc Dir From City:	Direction 2:
	Closest City:	X-Coordinate: 00301326
Badge #: 47-7	Miles From City:	Y-Coordinate: 04705322
Report Date: 05/26/2018	Road, Street, HWay:	Location Literal: US 20 AND M025/MARKET AVE
Officer Notified: 20:46 Hrs.	Definable Location:	Description:
Officer Arrived: 20:58 Hrs.	Milepost Number:	
Scene Investigated: YES		

Unit 001

Driver Name - Last: LEUSCHEN	Bus Use:	Transported to: CHEROKEE REGIONAL
First: ROBERT		
Middle: MATHIAS	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: HOLSTEIN AMBULANCE
City: HOLSTEIN		
State: IA	Traffic Controls: 04 - STOP SIGNS	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51025		
Suffix:	Point of Init Impact: 07 - REAR DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male		
Age: 69	Most Damaged Area: 07 - REAR DRIVER SIDE CORNER	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
CDL: NO		
License State: IA	Undrrid/Ovrid: 1 - NONE	
License Class: C	Rpr/Rplc Cost: \$2,500.00	
License Endorsmnt: B	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Restrictions: B	First Event: 33 - VEHICLE IN TRAFFIC	
Speed Limit: 55		Carrier Name:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event:	Carrier Address:
		Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL	Third Event:	Carrier State:
Alcohol Test Given: NO		Carrier Zip:
Drug Test Given: 1 - NONE	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 4		
Vehicle Year: 2018	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Number of Axles:
Vehicle Make: CHEVROLET - CHEV		HazMat Involvement:
Vehicle Model: EQUINOX LT AWD	Abg Switch Stat:	HazMat Placard:
Vehicle Style: SUV	Abg Deploy: 03 - NOT DEPLOYED	Placard #:
Vehicle Color: GOLD - GLD		HazMat Released?:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:
	Ejection: 2 - NOT EJECTED	GVWR:
Vehicle Defect: 01 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1:
	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 1:
Vehicle Action: 03 - TURNING RIGHT		Cit Chrg Code 2:
		Citation Charge 2:
Tow: 1 - DRIVEN AWAY		
		Citation Charge 3:
Tow #: 03 - SOUTH		
Initial Trvl Dir: 01 - NOT OBSCURED	Source of Trans: 03 - EMS GROUND	Citation Charge 4:
Vision Obscured: 01 - NOT OBSCURED	Died at Scene: 01 - NOT APPLICABLE	

Unit 002

Driver Name - Last: HASSAN	Bus Use:	Transported to: N/A
First: BASHIR		
Middle: ADBI	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: N/A
City: OMAHA		
State: NE	Traffic Controls: 04 - STOP SIGNS	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 68111		
Suffix:	Point of Init Impact: 01 - FRONT PASSENGER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 01 - FRONT PASSENGER SIDE CORNER	Cont. Circum., Drvr: 07 - FOLLOWED TOO CLOSE
Age: 43	Undrrid/Ovrid: 1 - NONE	
CDL: NO	Rpr/Rplc Cost: \$2,250.00	
License State: NE	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Class: O	First Event: 33 - VEHICLE IN TRAFFIC	
License Endorsmnt:		Carrier Name:
License Restrictions:		Carrier Address:
Speed Limit: 55	Second Event:	Carrier City:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER		Carrier State:
Driver Condition: 01 - APPARENTLY NORMAL	Third Event:	Carrier Zip:
Alcohol Test Given: NO		Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given: 1 - NONE	Fourth Event:	
Total Occupants: 1		Number of Axles:
Vehicle Year: 2011		HazMat Involvement:
Vehicle Make: FORD - FORD		HazMat Placard:
Vehicle Model: FUSION	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Placard #:
Vehicle Style: 4D		HazMat Released?:
Vehicle Color: BLACK - BLK	Abg Switch Stat:	Converter Dolly:
Vehicle Config: 01 - PASSENGER CAR	Abg Deploy: 03 - NOT DEPLOYED	GVWR:
Vehicle Defect: 01 - NONE		Cit Chrg Code 1:
	Trapped: 1 - NOT TRAPPED/APPLICABLE	Citation Charge 1:
Vehicle Action: 03 - TURNING RIGHT	Ejection: 2 - NOT EJECTED	
	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 2:
Tow: 1 - DRIVEN AWAY		Citation Charge 2:
	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	
Tow #:		Citation Charge 3:
Initial Trvl Dir: 03 - SOUTH		
Vision Obscured: 01 - NOT OBSCURED	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 03 - REAR END (FRONT TO REAR)	Environment: 01 - NONE APPARENT
Light Conditions: 2 - DUSK	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Workers Present:	

Narrative

Unit 1 was turning onto Hwy 20 from Market Avenue. Unit 2 struck the rear of unit 1. There is a stop sign at Market. the driver of Unit 2 was too close to Unit 1 to stop in allotted distance. the passenger of Unit 1 was transported to Cherokee Regional Hospital for complaints of neck and back pain. There were no other injuries and both vehicles were driven from the scene. Galva First responders assisted at the scene as did Holstein Ambulance who also transported the injured individual.

