

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-3866	Report to All Drivers:	At Intersection with:
Date of Acc: 06/04/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 00:36 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
Officer: STEHR MICHAEL	Acc Loc City:	Distance 2:
Badge #: 47-3	Acc Dir From City:	Direction 2:
Report Date: 06/04/2018	Closest City:	X-Coordinate: 00295634
Officer Notified: 00:36 Hrs.	Miles From City:	Y-Coordinate: 04691708
Officer Arrived: 09:57 Hrs.	Road, Street, HWay:	Location Literal: US 59 AND JASPER AVE
Scene Investigated: NO	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: HAYDEN	Bus Use:	Transported to: N/A
First: KATIE	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: N/A
Middle: ROSE	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
City: SCHLESWIG	Point of Init Impact: 01 - FRONT PASSENGER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
State: IA	Most Damaged Area: 01 - FRONT PASSENGER SIDE CORNER	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Zip: 51461	Undrrid/Ovrid: 1 - NONE	Carrier Name:
Suffix:	Rpr/Rplc Cost: \$1,000.00	Carrier Address:
Gender: Female	Ext of Damage: 2 - MINOR DAMAGE	Carrier City:
Age: 29	First Event: 31 - ANIMAL	Carrier State:
CDL: NO	Second Event:	Carrier Zip:
License State: IA	Third Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Class: C	Fourth Event:	Number of Axles:
License Endorsmnt: B	Most Harmful Event: 31 - ANIMAL	HazMat Involvement:
License Restrictions: B	Abg Switch Stat:	HazMat Placard:
Speed Limit: 55	Abg Deploy: 03 - NOT DEPLOYED	Placard #:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Released?:
Driver Condition: 01 - APPARENTLY NORMAL	Ejection: 1 - NOT APPLICABLE	Converter Dolly:
Alcohol Test Given: NO	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	GVWR:
Drug Test Given: 1 - NONE	Occpnt Protect: 99 - UNKNOWN	Cit Chrg Code 1:
Total Occupants: 1	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 1:
Vehicle Year: 2015	Died at Scene: 01 - NOT APPLICABLE	Cit Chrg Code 2:
Vehicle Make: DODGE - DODG		Citation Charge 2:
Vehicle Model: RAM		Citation Charge 3:
Vehicle Style: 1500		Citation Charge 4:
Vehicle Color: BLACK - BLK		
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)		
Vehicle Defect: 01 - NONE		
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT		
Tow: 1 - DRIVEN AWAY		
Tow #: 02 - EAST		
Initial Trvl Dir: 01 - NOT OBSCURED		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 06 - ANIMAL IN ROADWAY
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

unit 1 was eastbound on hwy 175. A deer ran out onto the road and Unit 1 struck the deer causing minor damage to the vehicle. Driver of Unit 1 reported the accident that night when it happened and then came into the Sheriffs Office the next day to fill out a report

