

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number:	<b>18-3928</b>	Report to All Drivers:		At Intersection with:	
Date of Acc:	<b>06/06/18</b>	Legal Intervention:	<b>NO</b>	Div HWay Trvl Dir:	
Time of Acc:	<b>05:20</b> Hrs.	Private Property:	<b>NO</b>	Distance 1:	
Name of Agency:	<b>IDA COUNTY SHERIFF'S OFFICE</b>	County:	<b>IDA - 47</b>	Direction 1:	
Officer:	<b>EHLERS ALEX</b>	Acc Loc City:		Distance 2:	
Badge #:	<b>47-10</b>	Acc Dir From City:		Direction 2:	
Report Date:	<b>06/06/2018</b>	Closest City:		X-Coordinate:	<b>00286781</b>
Officer Notified:	<b>05:20</b> Hrs.	Miles From City:		Y-Coordinate:	<b>04688712</b>
Officer Arrived:	<b>05:30</b> Hrs.	Road, Street, HWay:		Location Literal:	<b>STATE 175/IOWA 175</b>
Scene Investigated:	<b>NO</b>	Definable Location:		Description:	
		Milepost Number:			

**Unit 001**

Driver Name - Last:	<b>COLL KIRA</b>	Bus Use:		Transported to:	<b>N/A</b>
First:	<b>KIRA</b>	Dvr Distractions:	<b>02 - NOT DISTRACTED</b>	Transported by:	<b>N/A</b>
Middle:	<b>CHEYANNE</b>	Traffic Controls:	<b>01 - NO CONTROLS PRESENT</b>	Special Veh Func:	<b>01 - NO SPECIAL FUNCTION</b>
City:	<b>DANBURY</b>	Point of Init Impact:	<b>11 - FRONT DRIVER SIDE CORNER</b>	Emergency Status:	<b>01 - NOT APPLICABLE</b>
State:	<b>IA</b>	Most Damaged Area:	<b>11 - FRONT DRIVER SIDE CORNER</b>	Cont. Circum., Dvr:	<b>88 - NO IMPROPER ACTION</b>
Zip:	<b>51019-0000</b>	Undridd/Ovrid:	<b>1 - NONE</b>	Carrier Name:	
Suffix:		Rpr/Rplc Cost:	<b>\$4,000.00</b>	Carrier Address:	
Gender:	<b>Female</b>	Ext of Damage:	<b>2 - MINOR DAMAGE</b>	Carrier City:	
Age:	<b>24</b>	First Event:	<b>31 - ANIMAL</b>	Carrier State:	
CDL:	<b>NO</b>	Second Event:		Carrier Zip:	
License State:	<b>IA</b>	Third Event:		Cargo Body Type:	<b>01 - NOT APPLICABLE</b>
License Class:	<b>C</b>	Fourth Event:		Number of Axles:	
License Endorsmnt:		Most Harmful Event:	<b>31 - ANIMAL</b>	HazMat Involvement:	
License Restrictions:		Abg Switch Stat:		HazMat Placard:	
Speed Limit:	<b>55</b>	Abg Deploy:	<b>03 - NOT DEPLOYED</b>	Placard #:	
Seating Position:	<b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Trapped:	<b>1 - NOT TRAPPED/APPLICABLE</b>	HazMat Released?:	
Driver Condition:	<b>01 - APPARENTLY NORMAL</b>	Ejection:	<b>2 - NOT EJECTED</b>	Converter Dolly:	
Alcohol Test Given:	<b>NO</b>	Ejection Path:	<b>01 - NOT EJECTED/NOT APPLICABLE</b>	GVWR:	
Drug Test Given:	<b>1 - NONE</b>	Occpnt Protect:	<b>03 - SHOULDER AND LAP BELT USED</b>	Cit Chrg Code 1:	
Total Occupants:	<b>1</b>	Source of Trans:	<b>01 - NOT TRANSPORTED</b>	Citation Charge 1:	
Vehicle Year:	<b>2014</b>	Died at Scene:	<b>01 - NOT APPLICABLE</b>	Cit Chrg Code 2:	
Vehicle Make:	<b>TOYOTA - TOYT</b>			Citation Charge 2:	
Vehicle Model:	<b>SNA</b>			Citation Charge 3:	
Vehicle Style:	<b>VN</b>			Citation Charge 4:	
Vehicle Color:	<b>WHITE - WHI</b>				
Vehicle Config:	<b>04 - PASSENGER VAN (SEATS &lt;9)</b>				
Vehicle Defect:	<b>01 - NONE</b>				
Vehicle Action:	<b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>				
Tow:	<b>4 - NOT DISABLED - PRIVATELY ARRANGED</b>				
Tow #:					
Initial Trvl Dir:	<b>02 - EAST</b>				
Vision Obscured:	<b>01 - NOT OBSCURED</b>				

**Accident Environment**

First Harmful Event Loc:	<b>01 - ON ROADWAY</b>	Roadway Characteristics	
Manner of Crash/Collision:	<b>01 - NON-COLLISION (SINGLE VEHICLE)</b>	Environment:	<b>06 - ANIMAL IN ROADWAY</b>
Light Conditions:	<b>3 - DAWN</b>	Roadway:	<b>01 - NONE APPARENT</b>
Weather Conditions:	<b>01 - CLEAR</b>	Type of Road Junc/Feat:	<b>01 - NON-JUNCTION/NO SPECIAL FEATURE</b>
Surface Conditions:	<b>01 - DRY</b>	FRA No.:	
Workzone Related:	<b>NO</b>	Horizontal Alignment:	
Activity:		Vertical Alignment:	
Location:		First Harmful Evt of Crash:	<b>31 - ANIMAL</b>
Type:			
Workers Present:			

**Narrative**

unit 1 was heading east on HWY 175 when it struck a deer causing damage to the driver's side front end.