

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-4059	Report to All Drivers:	At Intersection with:
Date of Acc: 06/09/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 19:38 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
	Acc Loc City: HOLSTEIN - 3515	Distance 2:
Officer: MCMILLEN ROB	Acc Dir From City:	Direction 2:
	Closest City:	X-Coordinate: 00290980
Badge #: 47-7	Miles From City:	Y-Coordinate: 04706914
Report Date: 06/09/2018	Road, Street, HWay:	Location Literal: E PARK ST AND S KIEL ST
Officer Notified: 19:38 Hrs.	Definable Location:	Description:
Officer Arrived: 19:55 Hrs.	Milepost Number:	
Scene Investigated: YES		

Unit 001

Driver Name - Last: HANSEN	Bus Use:	Transported to: N/A
First: TYLAR		
Middle: JOHN	Drvr Distractions: 99 - UNKNOWN	Transported by: N/A
City: HOLSTEIN		
State: IA	Traffic Controls: 04 - STOP SIGNS	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51025-0000		
Suffix:	Point of Init Impact: 07 - REAR DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male		
Age: 23	Most Damaged Area: 07 - REAR DRIVER SIDE CORNER	Cont. Circum., Drvr: 99 - UNKNOWN
CDL: NO		
License State: IA	Undrrid/Ovrid: 1 - NONE	
License Class: C	Rpr/Rplc Cost: \$500.00	
License Endorsmnt:	Ext of Damage: 2 - MINOR DAMAGE	
License Restrictions:	First Event: 35 - PARKED MOTOR VEHICLE	
Speed Limit: 25		Carrier Name:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event:	Carrier Address:
		Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL	Third Event:	Carrier State:
Alcohol Test Given: NO		Carrier Zip:
Drug Test Given: 1 - NONE	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 1		
Vehicle Year: 2001	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	Number of Axles:
Vehicle Make: CHEVROLET - CHEV		HazMat Involvement:
Vehicle Model: TAH	Abg Switch Stat:	HazMat Placard:
Vehicle Style: SW	Abg Deploy: 03 - NOT DEPLOYED	Placard #:
Vehicle Color: GRAY - GRY		HazMat Released?:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:
	Ejection: 2 - NOT EJECTED	GVWR:
Vehicle Defect: 01 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1:
	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 1:
Vehicle Action: 09 - BACKING		
	5 - UNINJURED	Cit Chrg Code 2:
Tow: 1 - DRIVEN AWAY	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 2:
	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 3:
Tow #: 02 - EAST		
Initial Trvl Dir: 01 - NOT OBSCURED		Citation Charge 4:
Vision Obscured:		

Unit 002

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:	Traffic Controls: 04 - STOP SIGNS	Special Veh Func: 01 - NO SPECIAL FUNCTION
State:	Point of Init Impact: 07 - REAR DRIVER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Zip:	Most Damaged Area: 07 - REAR DRIVER SIDE CORNER	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION, 99 - UNKNOWN
Suffix:	Undrrid/Ovrid: 1 - NONE	
Gender:	Rpr/Rplc Cost: \$2,200.00	
Age: 21	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
CDL:	First Event: 35 - PARKED MOTOR VEHICLE	
License State:		Carrier Name:
License Class:		Carrier Address:
License Endorsmnt:		Carrier City:
License Restrictions:		Carrier State:
Speed Limit: 25		Carrier Zip:
Seating Position:	Second Event:	Cargo Body Type: 01 - NOT APPLICABLE
Driver Condition: 01 - APPARENTLY NORMAL	Third Event:	
Alcohol Test Given:	Fourth Event:	Number of Axles:
Drug Test Given:		HazMat Involvement:
Total Occupants: 0		HazMat Placard:
Vehicle Year: 2001	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	Placard #:
Vehicle Make: PONTIAC - PONT	Abg Switch Stat:	HazMat Released?:
Vehicle Model: GRA	Abg Deploy:	Converter Dolly:
Vehicle Style: 4D		GVWR:
Vehicle Color: SILVER - SIL	Trapped:	Cit Chrg Code 1:
Vehicle Config: 01 - PASSENGER CAR	Ejection:	Citation Charge 1:
Vehicle Defect: 01 - NONE	Ejection Path:	Cit Chrg Code 2:
Vehicle Action: 12 - LEGALLY PARKED	Occpnt Protect:	Citation Charge 2:
Tow: 1 - DRIVEN AWAY		
Tow #:	Source of Trans:	Citation Charge 3:
Initial Trvl Dir: 99 - UNKNOWN	Died at Scene:	Citation Charge 4:
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 08 - REAR TO REAR	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 35 - PARKED MOTOR VEHICLE
Type:	
Workers Present:	

Narrative

Unit 1 was backing up on Park street. Unit 1 didn't see Unit 2 and came into contact with Unit 1. Unit 1 was parked on Kiel Street. Information was exchanged at the scene.

Diagram

