

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **18-4091**
 Date of Acc: **06/10/18**
 Time of Acc: **22:12** Hrs.
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**
 Officer: **KINNAMAN KIRK**
 Badge #: **47-4**
 Report Date: **06/12/2018**
 Officer Notified: **22:12** Hrs.
 Officer Arrived: **22:16** Hrs.
 Scene Investigated: **NO**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **IDA - 47**
 Acc Loc City: **IDA GROVE - 3650**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00297771**
 Y-Coordinate: **04690530**
 Location Literal: **US 59**
 Description:

Unit 001

Driver Name - Last: PIERSON	Bus Use:	Transported to:
First: JOSHUA		
Middle: JAY	Dvrv Distractions: 02 - NOT DISTRACTED	Transported by:
City: IDA GROVE		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51445		
Suffix:	Point of Init Impact: 01 - FRONT PASSENGER SIDE CORNER	Emergency Status: 01 - NOT APPLICABLE
Gender: Male	Most Damaged Area: 01 - FRONT PASSENGER SIDE CORNER	Cont. Circum., Dvrv: 88 - NO IMPROPER ACTION
Age: 34	Undridd/Ovrid: 1 - NONE	
CDL: YES	Rpr/Rplc Cost: \$1,000.00	
License State: IA	Ext of Damage: 2 - MINOR DAMAGE	
License Class: A	First Event: 31 - ANIMAL	
License Endorsmnt: L		Carrier Name:
License Restrictions:		Carrier Address:
Speed Limit: 55	Second Event:	Carrier City:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Third Event:	Carrier State:
Driver Condition: 01 - APPARENTLY NORMAL	Fourth Event:	Carrier Zip:
Alcohol Test Given: NO		Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given: 1 - NONE	Most Harmful Event: 31 - ANIMAL	
Total Occupants: 1	Abg Switch Stat:	Number of Axles:
Vehicle Year: 2001	Abg Deploy: 03 - NOT DEPLOYED	HazMat Involvement:
Vehicle Make: FORD - FORD	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Placard:
Vehicle Model: EXCURSION LIMIT	Ejection: 1 - NOT APPLICABLE	Placard #:
Vehicle Style: UT	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	HazMat Released?:
Vehicle Color: BLUE - BLU	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Converter Dolly:
Vehicle Config: 03 - SPORT UTILITY VEHICLE		GVWR:
Vehicle Defect: 01 - NONE	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Tow: 1 - DRIVEN AWAY		Cit Chrg Code 2:
Tow #:		Citation Charge 2:
Initial Trvl Dir: 04 - WEST		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED		Citation Charge 4:

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 01 - NON-COLLISION (SINGLE VEHICLE)	Environment: 01 - NONE APPARENT
Light Conditions: 5 - DARK, ROADWAY NOT LIGHTED	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

Unit 1 was traveling westbound on Hwy 175 when a deer ran out in the road and in front of Unit 1. There was damage to the front passenger side and down the passenger side of Unit 1. Deer was off travel portion of road after impact.