

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **18-6439**
 Date of Acc: **09/05/18**
 Time of Acc: **07:25** Hrs.
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**
 Officer: **ANDERSON FRED**
 Badge #: **47-2**
 Report Date: **09/05/2018**
 Officer Notified: **07:39** Hrs.
 Officer Arrived: **07:53** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **YES**
 County: **IDA - 47**
 Acc Loc City: **HOLSTEIN - 3515**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00290948**
 Y-Coordinate: **04705641**
 Location Literal: **US 20**
 Description:

Unit 001

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Dvvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:		
State:	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip:		
Suffix:	Point of Init Impact: 08 - REAR DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender:		
Age:	Most Damaged Area: 08 - REAR DRIVER SIDE	Cont. Circum., Dvvr: 88 - NO IMPROPER ACTION
CDL:		
License State:	Undridd/Ovrid: 1 - NONE	
License Class:	Rpr/Rplc Cost: \$500.00	
License Endorsmnt:	Ext of Damage: 2 - MINOR DAMAGE	
License Restrictions:	First Event: 35 - PARKED MOTOR VEHICLE	
Speed Limit: 15		
Seating Position:		Carrier Name:
	Second Event:	Carrier Address:
Driver Condition: 98 - OTHER (EXPLAIN IN NARR		Carrier City:
Alcohol Test Given:	Third Event:	Carrier State:
Drug Test Given:		Carrier Zip:
Total Occupants: 2	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Vehicle Year: 1992		
Vehicle Make: FORD - FORD	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	Number of Axles:
Vehicle Model: E350		HazMat Involvement:
Vehicle Style: MOTOR HOME	Abg Switch Stat:	HazMat Placard:
Vehicle Color: WHITE - WHI	Abg Deploy:	Placard #:
Vehicle Config: 21 - MOTOR HOME/RECREATIONAL VEHICL	Trapped:	HazMat Released?:
Vehicle Defect: 01 - NONE	Ejection:	Converter Dolly:
	Ejection Path:	GVWR:
Vehicle Action: 12 - LEGALLY PARKED	Occpnt Protect:	Cit Chrg Code 1:
		Citation Charge 1:
Tow: 1 - DRIVEN AWAY		Cit Chrg Code 2:
		Citation Charge 2:
Tow #:		
Initial Trvl Dir: 04 - WEST	Source of Trans:	Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED	Died at Scene:	Citation Charge 4:

Unit 002

Driver Name - Last: ABDYRAZAKOV	Bus Use:	Transported to: NONE
First: NURBEK		
Middle:	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: NONE
City: CHICAGO		
State: IL	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 60618-0000		
Suffix:	Point of Init Impact: 08 - REAR DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male		
Age: 31	Most Damaged Area: 08 - REAR DRIVER SIDE	Cont. Circum., Drvr: 98 - OTHER (EXPLAIN IN NARRATIVE)
CDL:	Undrriid/Ovrid: 1 - NONE	
License State: IL	Rpr/Rplc Cost: \$200.00	
License Class: A	Ext of Damage: 2 - MINOR DAMAGE	
License Endorsmnt:	First Event: 35 - PARKED MOTOR VEHICLE	
License Restrictions: BE		Carrier Name:
Speed Limit: 15	Second Event:	Carrier Address:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER		Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL	Third Event:	Carrier State:
Alcohol Test Given: NO		Carrier Zip:
Drug Test Given: 1 - NONE	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 1		
Vehicle Year: 2019	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	Number of Axles:
Vehicle Make: VOLVO - VOLV		HazMat Involvement:
Vehicle Model: SEMI TRACTOR	Abg Switch Stat:	HazMat Placard:
Vehicle Style: TR	Abg Deploy: 01 - NOT APPLICABLE	Placard #:
Vehicle Color: MAROON, BURGUNDY (PURPL	Trapped: 1 - NOT TRAPPED/APPLICABLE	HazMat Released?:
Vehicle Config: 13 - TRACTOR/SEMI-TRAILER	Ejection: 2 - NOT EJECTED	Converter Dolly:
Vehicle Defect: 01 - NONE	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	GVWR:
	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Cit Chrg Code 1:
Vehicle Action: 01 - MOVEMENT ESSENTIALLY STRAIGHT	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 1:
Tow: 1 - DRIVEN AWAY	Died at Scene: 01 - NOT APPLICABLE	Cit Chrg Code 2:
		Citation Charge 2:
Tow #:		Cit Chrg Code 3:
Initial Trvl Dir: 02 - EAST		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED		Citation Charge 4:

Accident Environment

First Harmful Event Loc: 07 - IN PARKING LANE/ZONE	Roadway Characteristics
Manner of Crash/Collision: 07 - SIDESWIPE, OPPOSITE DIRECTION	Environment: 01 - NONE APPARENT
Light Conditions: 2 - DUSK	Roadway: 01 - NONE APPARENT
Weather Conditions: 05 - RAIN	
	Type of Road Junc/Feat: 96 - OTHER NON-INTERSECTION (EXPLAIN IN NARRATIVE)
Surface Conditions: 02 - WET	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 35 - PARKED MOTOR VEHICLE
Workers Present:	

Narrative

Unit #1 was legally parked at the Holstein Travel Center. Unit #2 was parked next to Unit #1. Unit #2 was attempting to drive from the parking space when the trailer attached to Unit #2 side swiped Unit #1, causing minor damage to both vehicles.

Travel Center Holstein Iowa
Parking Lot

