

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: <b>18-6562</b>	Report to All Drivers:	At Intersection with:
Date of Acc: <b>09/09/18</b>	Legal Intervention: <b>NO</b>	Div HWay Trvl Dir:
Time of Acc: <b>11:35</b> Hrs.	Private Property: <b>NO</b>	Distance 1:
Name of Agency: <b>IDA COUNTY SHERIFF'S OFFICE</b>	County: <b>IDA - 47</b>	Direction 1:
Officer: <b>STEHR MICHAEL</b>	Acc Loc City:	Distance 2:
Badge #: <b>47-3</b>	Acc Dir From City:	Direction 2:
Report Date: <b>09/09/2018</b>	Closest City:	X-Coordinate: <b>00284283</b>
Officer Notified: <b>11:35</b> Hrs.	Miles From City:	Y-Coordinate: <b>04686881</b>
Officer Arrived: <b>11:47</b> Hrs.	Road, Street, HWay:	Location Literal: <b>STATE 175/IOWA 175</b>
Scene Investigated: <b>YES</b>	Definable Location:	Description:
	Milepost Number:	

**Unit 001**

Driver Name - Last: <b>SOHM</b>	Bus Use:	Transported to:
First: <b>TINA</b>		
Middle: <b>MARIE</b>	Dvrv Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City: <b>DANBURY</b>	Traffic Controls:	Special Veh Func:
State: <b>IA</b>	Point of Init Impact:	Emergency Status:
Zip: <b>51019-0000</b>	Most Damaged Area:	Cont. Circum., Dvrv: <b>88 - NO IMPROPER ACTION</b>
Suffix:	Undrrid/Ovrid:	
Gender: <b>Female</b>	Rpr/Rplc Cost: <b>\$3,000.00</b>	Carrier Name:
Age: <b>43</b>	Ext of Damage:	Carrier Address:
CDL: <b>NO</b>	First Event:	Carrier City:
License State: <b>IA</b>	Second Event:	Carrier State:
License Class: <b>D</b>	Third Event:	Carrier Zip:
License Endorsmnt: <b>3 - PASS VEH LESS THAN 16 PA</b>	Fourth Event:	Cargo Body Type: <b>01 - NOT APPLICABLE</b>
License Restrictions: <b>B</b>	Most Harmful Event:	Number of Axles:
Speed Limit:	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
Driver Condition:	Trapped:	Placard #:
Alcohol Test Given: <b>NO</b>	Ejection:	HazMat Released?:
Drug Test Given: <b>1 - NONE</b>	Ejection Path:	Converter Dolly:
Total Occupants: <b>1</b>	Occpnt Protect:	GVWR:
Vehicle Year: <b>2005</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Cit Chrg Code 1:
Vehicle Make: <b>FORD - FORD</b>	Died at Scene: <b>01 - NOT APPLICABLE</b>	Citation Charge 1:
Vehicle Model: <b>F15</b>		Cit Chrg Code 2:
Vehicle Style: <b>PK</b>		Citation Charge 2:
Vehicle Color: <b>SILVER - SIL</b>		Citation Charge 3:
Vehicle Config: <b>02 - FOUR-TIRE TRUCK (PICK-UP)</b>		Citation Charge 4:
Vehicle Defect:		
Vehicle Action:		
Tow: <b>1 - DRIVEN AWAY</b>		
Tow #:		
Initial Trvl Dir:		
Vision Obscured:		

**Accident Environment**

First Harmful Event Loc:	<b>Roadway Characteristics</b>
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>31 - ANIMAL</b>
Type:	
Workers Present:	

**Narrative**

UNIT 1 WAS TRAVELING EAST BOUND ON HWY 175. AN APPROACHING SEMI WITH TRAILER WAS HEADED WESTBOUND. WHEN UNIT 1 WAS MEETING THE SEMI, A DEER RAN OUT FROM BEHIND THE SEMI AND STRUCK UNIT 1 IN THE FRONT DRIVERS SIDE. UNIT 1 DID NOT SEE THE DEER UNTIL IT WAS TOO LATE.

