

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-6593	Report to All Drivers: NO	At Intersection with:
Date of Acc: 09/10/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 17:53 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
	Acc Loc City: IDA GROVE - 3650	Distance 2:
Officer: MCMILLEN ROB	Acc Dir From City:	Direction 2:
	Closest City:	X-Coordinate: 00296440
Badge #: 47-7	Miles From City:	Y-Coordinate: 04691130
Report Date: 09/10/2018	Road, Street, HWay:	Location Literal: MAIN ST AND MOOREHEAD AVE
Officer Notified: 17:53 Hrs.	Definable Location:	Description: AND 1ST ST
Officer Arrived: 17:53 Hrs.	Milepost Number:	
Scene Investigated: YES		

Unit 001

Driver Name - Last: KORNER	Bus Use:	Transported to: N/A
First: WAYNE		
Middle: THEODORE CARL	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: N/A
City: IDA GROVE		
State: IA	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip: 51445-0000		
Suffix:	Point of Init Impact: 03 - MIDDLE PASSENGER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender: Male		
Age: 83	Most Damaged Area: 03 - MIDDLE PASSENGER SIDE	Cont. Circum., Drvr: 98 - OTHER (EXPLAIN IN NARRATIVE)
CDL: NO		
License State: IA	Undridd/Ovrid: 1 - NONE	
License Class: C	Rpr/Rplc Cost: \$200.00	
License Endorsmnt:	Ext of Damage: 2 - MINOR DAMAGE	
License Restrictions:	First Event: 35 - PARKED MOTOR VEHICLE	
Speed Limit: 25		Carrier Name:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Second Event:	Carrier Address:
		Carrier City:
Driver Condition: 01 - APPARENTLY NORMAL	Third Event:	Carrier State:
Alcohol Test Given: NO		Carrier Zip:
Drug Test Given: 1 - NONE	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
Total Occupants: 2		
Vehicle Year: 2017	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	Number of Axles:
Vehicle Make: GENERAL MOTORS - GMC		HazMat Involvement:
Vehicle Model: SRA	Abg Switch Stat:	HazMat Placard:
Vehicle Style: PK	Abg Deploy: 03 - NOT DEPLOYED	Placard #:
Vehicle Color: BLACK - BLK		HazMat Released?:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)	Trapped: 1 - NOT TRAPPED/APPLICABLE	Converter Dolly:
Vehicle Defect: 01 - NONE	Ejection: 2 - NOT EJECTED	GVWR:
	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Cit Chrg Code 1:
Vehicle Action: 03 - TURNING RIGHT	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	Citation Charge 1:
Tow: 1 - DRIVEN AWAY		Cit Chrg Code 2:
		Citation Charge 2:
Tow #: 04 - WEST		
Initial Trvl Dir: 01 - NOT OBSCURED		Citation Charge 3:
Vision Obscured:		
	Source of Trans: 01 - NOT TRANSPORTED	Citation Charge 4:
	Died at Scene: 01 - NOT APPLICABLE	

Unit 002

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:		
State:	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip:		
Suffix:	Point of Init Impact: 08 - REAR DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender:		
Age:	Most Damaged Area: 08 - REAR DRIVER SIDE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
CDL:	Undrrid/Ovrid: 1 - NONE	
License State:	Rpr/Rplc Cost: \$1,300.00	
License Class:	Ext of Damage: 2 - MINOR DAMAGE	
License Endorsmnt:	First Event: 35 - PARKED MOTOR VEHICLE	
License Restrictions:		Carrier Name:
Speed Limit: 25		Carrier Address:
Seating Position:		Carrier City:
	Second Event:	Carrier State:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier Zip:
Alcohol Test Given:	Third Event:	Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given:		
Total Occupants: 0	Fourth Event:	Number of Axles:
Vehicle Year:		HazMat Involvement:
Vehicle Make: CHEVROLET - CHEV		HazMat Placard:
Vehicle Model: EQUINOX		Placard #:
Vehicle Style: SUV	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	HazMat Released?:
Vehicle Color: BLACK - BLK		Converter Dolly:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Abg Switch Stat:	GVWR:
	Abg Deploy:	Cit Chrg Code 1:
Vehicle Defect: 01 - NONE		Citation Charge 1:
Vehicle Action: 12 - LEGALLY PARKED	Trapped:	
	Ejection:	Cit Chrg Code 2:
Tow: 1 - DRIVEN AWAY	Ejection Path:	Citation Charge 2:
Tow #:	Occpnt Protect:	
Initial Trvl Dir: 04 - WEST		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED		
	Source of Trans:	
	Died at Scene:	Citation Charge 4:

Accident Environment

First Harmful Event Loc: 06 - OUTSIDE TRAFFICWAY	Roadway Characteristics
Manner of Crash/Collision: 06 - SIDESWIPE, SAME DIRECTION	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 01 - CLEAR	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 01 - DRY	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 35 - PARKED MOTOR VEHICLE
Workers Present:	

Narrative

Unit 1 was pulling into a parking space and got too close to Unit 2. Unit 2 was parked in a parking space. The two units came into contact with each other. There were fire trucks giving rides to kids so I don't know if that caused any distraction to driver of unit 1 or if he just missed judged the distance between the two units. No one was injured and both owners were given accident reports.

