

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: **18-6661**  
 Date of Acc: **09/13/18**  
 Time of Acc: **19:54** Hrs.  
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**  
 Officer: **KINNAMAN KIRK**  
 Badge #: **47-4**  
 Report Date: **09/14/2018**  
 Officer Notified: **19:55** Hrs.  
 Officer Arrived: **20:04** Hrs.  
 Scene Investigated: **YES**

Report to All Drivers:  
 Legal Intervention: **NO**  
 Private Property: **NO**  
 County: **IDA - 47**  
 Acc Loc City:  
 Acc Dir From City:  
 Closest City:  
 Miles From City:  
 Road, Street, HWay:  
 Definable Location:  
 Milepost Number:

At Intersection with:  
 Div HWay Trvl Dir:  
 Distance 1:  
 Direction 1:  
 Distance 2:  
 Direction 2:  
 X-Coordinate: **00293088**  
 Y-Coordinate: **04705576**  
 Location Literal: **US 20 AND US 59**  
 Description:

**Unit 001**

Driver Name - Last: **WELLS**  
 First: **JOHN**  
 Middle: **C**  
 City:  
 State:  
 Zip:  
 Suffix:  
 Gender:  
 Age:  
 CDL:  
 License State:  
 License Class:  
 License Endorsmnt:  
 License Restrictions:  
 Speed Limit:  
 Seating Position:  
 Driver Condition:  
 Alcohol Test Given: **NO**  
 Drug Test Given: **1 - NONE**  
 Total Occupants: **1**  
 Vehicle Year: **2008**  
 Vehicle Make: **CHRYSLER - CHRY**  
 Vehicle Model: **PT LIMITED**  
 Vehicle Style: **VAN**  
 Vehicle Color: **WHITE - WHI**  
 Vehicle Config: **03 - SPORT UTILITY VEHICLE**  
 Vehicle Defect:  
 Vehicle Action:  
 Tow: **3 - DISABLED - OFFICER ARRANGED**  
 Tow #: **50**  
 Initial Trvl Dir:  
 Vision Obscured:

Bus Use:  
 Dvr Distractions: **15 - INATTENTIVE/LOST IN THOUGHT**  
 Traffic Controls:  
 Point of Init Impact:  
 Most Damaged Area:  
 Undrrid/Ovrid:  
 Rpr/Rplc Cost: **\$5,000.00**  
 Ext of Damage:  
 First Event:  
 Second Event:  
 Third Event:  
 Fourth Event:  
 Most Harmful Event:  
 Abg Switch Stat:  
 Abg Deploy:  
 Trapped:  
 Ejection:  
 Ejection Path:  
 Occpnt Protect:  
 Source of Trans: **03 - EMS GROUND**  
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:  
 Transported by:  
 Special Veh Func:  
 Emergency Status:  
 Cont. Circum., Dvr: **88 - NO IMPROPER ACTION**  
 Carrier Name:  
 Carrier Address:  
 Carrier City:  
 Carrier State:  
 Carrier Zip:  
 Cargo Body Type: **01 - NOT APPLICABLE**  
 Number of Axles:  
 HazMat Involvement:  
 HazMat Placard:  
 Placard #:  
 HazMat Released?:  
 Converter Dolly:  
 GVWR:  
 Cit Chrg Code 1:  
 Citation Charge 1:  
 Cit Chrg Code 2:  
 Citation Charge 2:  
 Citation Charge 3:  
 Citation Charge 4:

**Accident Environment**

First Harmful Event Loc:  
 Manner of Crash/Collision:  
 Light Conditions:  
 Weather Conditions:  
 Surface Conditions:  
 Workzone Related:  
 Activity:  
 Location:  
 Type:  
 Workers Present:

**Roadway Characteristics**  
 Environment:  
 Roadway:  
 Type of Road Junc/Feat:  
 FRA No.:  
 Horizontal Alignment:  
 Vertical Alignment:  
 First Harmful Evt of Crash: **31 - ANIMAL**

**Narrative**

Unit 1 was traveling north on Hwy 59 and didnt notice the intersection for Hwy 20. ran through the stop sign and into the corn field. went 16 rows into the corn field north of Hwy 20.