

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number:	18-6776	Report to All Drivers:		At Intersection with:	
Date of Acc:	09/05/18	Legal Intervention:	NO	Div HWay Trvl Dir:	
Time of Acc:	12:45 Hrs.	Private Property:	YES	Distance 1:	
Name of Agency:	IDA COUNTY SHERIFF'S OFFICE	County:	IDA - 47	Direction 1:	
Officer:	STEHR MICHAEL	Acc Loc City:	HOLSTEIN - 3515	Distance 2:	
Badge #:	47-3	Acc Dir From City:		Direction 2:	
Report Date:	09/18/2018	Closest City:		X-Coordinate:	00291184
Officer Notified:	13:05 Hrs.	Miles From City:		Y-Coordinate:	04708716
Officer Arrived:	13:24 Hrs.	Road, Street, HWay:		Location Literal:	N LUBECK ST
Scene Investigated:	NO	Definable Location:		Description:	
		Milepost Number:			

Unit 001

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:	Traffic Controls:	Special Veh Func:
State:	Point of Init Impact:	Emergency Status:
Zip:	Most Damaged Area:	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Suffix:	Undrrid/Ovrid:	
Gender:	Rpr/Rplc Cost: \$1,700.00	Carrier Name:
Age:	Ext of Damage:	Carrier Address:
CDL:	First Event:	Carrier City:
License State:	Second Event:	Carrier State:
License Class:	Third Event:	Carrier Zip:
License Endorsmnt:	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions:	Most Harmful Event:	Number of Axles:
Speed Limit:	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
Driver Condition:	Trapped:	Placard #:
Alcohol Test Given: NO	Ejection:	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path:	Converter Dolly:
Total Occupants:	Occpnt Protect:	GVWR:
Vehicle Year: 2010	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Make: CHEVROLET - CHEV	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Model: SLV		Cit Chrg Code 2:
Vehicle Style: PK		Citation Charge 2:
Vehicle Color: BLACK - BLK		Citation Charge 3:
Vehicle Config: 02 - FOUR-TIRE TRUCK (PICK-UP)		Citation Charge 4:
Vehicle Defect:		
Vehicle Action:		
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir:		
Vision Obscured:		

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

unit 1 was in the North parking lot of VT Industries. He was in a parking spot and noticed that his passenger side front door was damaged on the bottom. Unclear on how this happened and no suspect vehicle at this time to report.

