

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **18-6940**
 Date of Acc: **09/25/18**
 Time of Acc: **11:45** Hrs.
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**
 Officer: **TRUCKE COREY**
 Badge #: **47-6**
 Report Date: **09/25/2018**
 Officer Notified: **13:44** Hrs.
 Officer Arrived: **14:17** Hrs.
 Scene Investigated: **NO**

Report to All Drivers: **NO**
 Legal Intervention: **NO**
 Private Property: **YES**
 County: **IDA - 47**
 Acc Loc City: **HOLSTEIN - 3515**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00290497**
 Y-Coordinate: **04707347**
 Location Literal: **HANOVER ST**
 Description:

Unit 001

Driver Name - Last: **THORBORG**
 First: **DAVID**
 Middle: **ELMER**
 City: **GALVA**
 State: **IA**
 Zip: **51020-0000**
 Suffix:
 Gender: **Male**
 Age: **48**
 CDL: **YES**
 License State: **IA**
 License Class: **A**
 License Endorsmnt: **NPS**
 License Restrictions: **BM**
 Speed Limit: **25**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2008**
 Vehicle Make: **THOM**
 Vehicle Model: **310TS**
 Vehicle Style: **SCHOOLBUS**
 Vehicle Color: **YELLOW - YEL**
 Vehicle Config: **22 - SCHOOL BUS (SEATS >15)**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **09 - BACKING**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **02 - EAST**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use: **01 - SCHOOL (PUBLIC OR PRIVATE)**
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **07 - REAR DRIVER SIDE CORNER**
 Most Damaged Area: **07 - REAR DRIVER SIDE CORNER**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$200.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **35 - PARKED MOTOR VEHICLE**
 Second Event:
 Third Event:
 Fourth Event:
 Most Harmful Event: **35 - PARKED MOTOR VEHICLE**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**
5 - UNINJURED

Transported to:
 Transported by:
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **98 - OTHER (EXPLAIN IN NARRATIVE)**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **20 - BUS**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last:	Bus Use:	Transported to:
First:		
Middle:	Drvr Distractions: 01 - NOT APPLICABLE/NO DRIVER	Transported by:
City:		
State:	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
Zip:		
Suffix:	Point of Init Impact: 08 - REAR DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
Gender:		
Age:	Most Damaged Area: 08 - REAR DRIVER SIDE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
CDL:	Undrrid/Ovrid: 1 - NONE	
License State:	Rpr/Rplc Cost: \$2,000.00	
License Class:	Ext of Damage: 3 - FUNCTIONAL DAMAGE	
License Endorsmnt:	First Event: 35 - PARKED MOTOR VEHICLE	
License Restrictions:		Carrier Name:
Speed Limit: 25		Carrier Address:
Seating Position:		Carrier City:
	Second Event:	Carrier State:
Driver Condition: 01 - APPARENTLY NORMAL		Carrier Zip:
Alcohol Test Given:	Third Event:	Cargo Body Type: 01 - NOT APPLICABLE
Drug Test Given:		
Total Occupants: 0	Fourth Event:	Number of Axles:
Vehicle Year: 2014		HazMat Involvement:
Vehicle Make: BUICK - BUIC		HazMat Placard:
Vehicle Model: ENCORE CONVENIE		Placard #:
Vehicle Style: PC	Most Harmful Event: 35 - PARKED MOTOR VEHICLE	HazMat Released?:
Vehicle Color: GRAY - GRY		Converter Dolly:
Vehicle Config: 03 - SPORT UTILITY VEHICLE	Abg Switch Stat:	GVWR:
	Abg Deploy:	Cit Chrg Code 1:
Vehicle Defect: 01 - NONE		Citation Charge 1:
Vehicle Action: 12 - LEGALLY PARKED	Trapped:	
	Ejection:	Cit Chrg Code 2:
Tow: 1 - DRIVEN AWAY	Ejection Path:	Citation Charge 2:
Tow #:	Occpnt Protect:	
Initial Trvl Dir: 99 - UNKNOWN		Citation Charge 3:
Vision Obscured: 01 - NOT OBSCURED		
	Source of Trans:	Citation Charge 4:
	Died at Scene:	

Accident Environment

First Harmful Event Loc: 07 - IN PARKING LANE/ZONE	Roadway Characteristics
Manner of Crash/Collision: 98 - OTHER (EXPLAIN IN NARRATIVE)	Environment: 01 - NONE APPARENT
Light Conditions: 1 - DAYLIGHT	Roadway: 01 - NONE APPARENT
Weather Conditions: 02 - CLOUDY	
	Type of Road Junc/Feat: 01 - NON-JUNCTION/NO SPECIAL FEATURE
Surface Conditions: 02 - WET	
	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: 35 - PARKED MOTOR VEHICLE
Workers Present:	

Narrative

Unit 1 had pulled into a driveway at 213 Hanover St. While unit 1 was in the driveway, unit 2 pulled in and parked next to unit 1. The driver of unit 1 was not aware that unit 2 had pulled in. When the driver of unit 1 backed out of the driveway, it clipped the bumper on unit 2 causing damage to both vehicles.