

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-7842	Report to All Drivers:	At Intersection with:
Date of Acc: 11/01/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 21:55 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
Officer: VAN EGDOM BRADY	Acc Loc City:	Distance 2:
Badge #: 47-5	Acc Dir From City:	Direction 2:
Report Date: 11/02/2018	Closest City:	X-Coordinate: 00289520
Officer Notified: 21:55 Hrs.	Miles From City:	Y-Coordinate: 04690078
Officer Arrived: 21:55 Hrs.	Road, Street, HWay:	Location Literal: STATE 175/IOWA 175 AND FAITH
Scene Investigated: NO	Definable Location:	Description: AVE
	Milepost Number:	

Unit 001

Driver Name - Last: MILLER	Bus Use:	Transported to:
First: DARYL		
Middle: ALAN	Dvr Distractions: 02 - NOT DISTRACTED	Transported by:
City: BATTLE CREEK	Traffic Controls:	Special Veh Func:
State: IA	Point of Init Impact:	Emergency Status:
Zip: 51006	Most Damaged Area:	Cont. Circum., Dvr: 88 - NO IMPROPER ACTION
Suffix:	Undrrid/Ovrid:	
Gender: Male	Rpr/Rplc Cost: \$5,000.00	Carrier Name:
Age: 72	Ext of Damage:	Carrier Address:
CDL: YES	First Event:	Carrier City:
License State: IA	Second Event:	Carrier State:
License Class: A	Third Event:	Carrier Zip:
License Endorsmnt: K	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions: K	Most Harmful Event:	Number of Axles:
Speed Limit:	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
Driver Condition:	Trapped:	Placard #:
Alcohol Test Given: NO	Ejection:	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path:	Converter Dolly:
Total Occupants: 1	Occpnt Protect:	GVWR:
Vehicle Year: 2017	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Make: HYUNDAI - HYUN	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Model: IONIQ BLUE		Citation Charge 2:
Vehicle Style: 4D		Citation Charge 3:
Vehicle Color: BLACK - BLK		Citation Charge 4:
Vehicle Color: BLACK - BLK		
Vehicle Config: 01 - PASSENGER CAR		
Vehicle Defect:		
Vehicle Action:		
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir:		
Vision Obscured:		


Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

UNIT 1 WAS TRAVELING WEST ON HIGHWAY 175 NEAR THE INTERSECTION OF FAITH AVENUE. A DEER THEN EXITED THE SOUTH DITCH AND ENTERED THE ROADWAY. UNIT 1 WAS UNABLE TO AVOID THE DEER, STRIKING THE DEER WITH THE FRONT PASSENGER SIDE OF THE VEHICLE.

Diagram



NOT TO SCALE

