

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 18-7935	Report to All Drivers:	At Intersection with:
Date of Acc: 11/06/18	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 07:55 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
Officer: VAN EGDOM BRADY	Acc Loc City:	Distance 2:
Badge #: 47-5	Acc Dir From City:	Direction 2:
Report Date: 11/06/2018	Closest City:	X-Coordinate: 00293552
Officer Notified: 07:55 Hrs.	Miles From City:	Y-Coordinate: 04693968
Officer Arrived: 08:00 Hrs.	Road, Street, HWay:	Location Literal: US 59 AND 230TH ST
Scene Investigated: NO	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: HARRIMAN	Bus Use:	Transported to:
First: LEAH		
Middle: RENAE	Dvrv Distractions: 02 - NOT DISTRACTED	Transported by:
City: HOLSTEIN	Traffic Controls:	Special Veh Func:
State: IA	Point of Init Impact:	Emergency Status:
Zip: 51025	Most Damaged Area:	Cont. Circum., Dvrv: 88 - NO IMPROPER ACTION
Suffix:	Undrrid/Ovrid:	
Gender: Female	Rpr/Rplc Cost: \$7,000.00	Carrier Name:
Age: 43	Ext of Damage:	Carrier Address:
CDL: NO	First Event:	Carrier City:
License State: IA	Second Event:	Carrier State:
License Class: C	Third Event:	Carrier Zip:
License Endorsmnt: B	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions: B	Most Harmful Event:	Number of Axles:
Speed Limit:	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
Driver Condition:	Trapped:	Placard #:
Alcohol Test Given: NO	Ejection:	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path:	Converter Dolly:
Total Occupants: 1	Occpnt Protect:	GVWR:
Vehicle Year: 2012	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Make: CHEVROLET - CHEV	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Model: TRAVERSE		Cit Chrg Code 2:
Vehicle Style: SUV		Citation Charge 2:
Vehicle Color: WHITE - WHI		Citation Charge 3:
Vehicle Config: 03 - SPORT UTILITY VEHICLE		Citation Charge 4:
Vehicle Defect:		
Vehicle Action:		
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir:		
Vision Obscured:		

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

UNIT 1 WAS TRAVELING SOUTH ON HWY. 59 NEAR THE INTERSECTION OF 230TH ST. A DEER THEN EXITED THE DITCH AND ENTERED THE ROADWAY. UNIT 1 WAS UNABLE TO AVOID THE DEER, STRIKING THE DEER WITH THE FRONT PASSENGER SIDE OF THE VEHICLE.

Diagram

