

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: **18-7945**  
 Date of Acc: **11/06/18**  
 Time of Acc: **15:58** Hrs.  
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**  
 Officer: **VAN EGDOM BRADY**  
 Badge #: **47-5**  
 Report Date: **11/06/2018**  
 Officer Notified: **15:59** Hrs.  
 Officer Arrived: **16:17** Hrs.  
 Scene Investigated: **YES**

Report to All Drivers:  
 Legal Intervention: **NO**  
 Private Property: **YES**  
 County: **IDA - 47**  
 Acc Loc City: **HOLSTEIN - 3515**  
 Acc Dir From City:  
 Closest City:  
 Miles From City:  
 Road, Street, HWay:  
 Definable Location:  
 Milepost Number:

At Intersection with:  
 Div HWay Trvl Dir:  
 Distance 1:  
 Direction 1:  
 Distance 2:  
 Direction 2:  
 X-Coordinate: **00291348**  
 Y-Coordinate: **04707051**  
 Location Literal: **DAVENPORT ST**  
 Description:

**Unit 001**

Driver Name - Last: **TODD**  
 First: **SHANTEL**  
 Middle: **MARIE**  
 City: **HOLSTEIN**  
 State: **IA**  
 Zip: **51025-0000**  
 Suffix:  
 Gender: **Female**  
 Age: **27**  
 CDL: **NO**  
 License State: **IA**  
 License Class: **C**  
 License Endorsmnt:  
 License Restrictions:  
 Speed Limit: **15**  
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**  
 Driver Condition: **01 - APPARENTLY NORMAL**  
 Alcohol Test Given: **NO**  
 Drug Test Given: **1 - NONE**  
 Total Occupants: **1**  
 Vehicle Year: **2015**  
 Vehicle Make: **CHEVROLET - CHEV**  
 Vehicle Model: **MAL**  
 Vehicle Style: **4D**  
 Vehicle Color: **BLACK - BLK**  
 Vehicle Config: **01 - PASSENGER CAR**  
 Vehicle Defect: **01 - NONE**  
 Vehicle Action: **09 - BACKING**  
 Tow: **1 - DRIVEN AWAY**  
 Tow #:  
 Initial Trvl Dir: **01 - NORTH**  
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:  
 Dvr Distractions: **02 - NOT DISTRACTED**  
 Traffic Controls: **01 - NO CONTROLS PRESENT**  
 Point of Init Impact: **06 - REAR MIDDLE**  
 Most Damaged Area: **06 - REAR MIDDLE**  
 Undrrid/Ovrid: **1 - NONE**  
 Rpr/Rplc Cost: **\$1,000.00**  
 Ext of Damage: **2 - MINOR DAMAGE**  
 First Event: **33 - VEHICLE IN TRAFFIC**  
 Second Event:  
 Third Event:  
 Fourth Event:  
 Most Harmful Event: **33 - VEHICLE IN TRAFFIC**  
 Abg Switch Stat:  
 Abg Deploy: **03 - NOT DEPLOYED**  
 Trapped: **1 - NOT TRAPPED/APPLICABLE**  
 Ejection: **1 - NOT APPLICABLE**  
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**  
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**  
 Source of Trans: **01 - NOT TRANSPORTED**  
 Died at Scene: **01 - NOT APPLICABLE**

Transported to:  
 Transported by:  
 Special Veh Func: **01 - NO SPECIAL FUNCTION**  
 Emergency Status: **01 - NOT APPLICABLE**  
 Cont. Circum., Dvr: **99 - UNKNOWN**  
 Carrier Name:  
 Carrier Address:  
 Carrier City:  
 Carrier State:  
 Carrier Zip:  
 Cargo Body Type: **01 - NOT APPLICABLE**  
 Number of Axles:  
 HazMat Involvement:  
 HazMat Placard:  
 Placard #:  
 HazMat Released?:  
 Converter Dolly:  
 GVWR:  
 Cit Chrg Code 1:  
 Citation Charge 1:  
 Cit Chrg Code 2:  
 Citation Charge 2:  
 Citation Charge 3:  
 Citation Charge 4:

**Unit 002**

Driver Name - Last: <b>WINKEL</b>	Bus Use:	Transported to:
First: <b>KOLE</b>		
Middle: <b>ALLEN</b>	Drvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by:
City: <b>HOLSTEIN</b>		
State: <b>IA</b>	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>51025-0000</b>		
Suffix:	Point of Init Impact: <b>09 - MIDDLE DRIVER SIDE</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Male</b>	Most Damaged Area: <b>09 - MIDDLE DRIVER SIDE</b>	Cont. Circum., Drvr: <b>99 - UNKNOWN</b>
Age: <b>16</b>	Undrrid/Ovrid: <b>1 - NONE</b>	
CDL: <b>NO</b>	Rpr/Rplc Cost: <b>\$1,500.00</b>	
License State: <b>IA</b>	Ext of Damage: <b>2 - MINOR DAMAGE</b>	
License Class: <b>C</b>	First Event: <b>33 - VEHICLE IN TRAFFIC</b>	Carrier Name:
License Endorsmnt:		Carrier Address:
License Restrictions: <b>7B</b>	Second Event:	Carrier City:
Speed Limit: <b>15</b>	Third Event:	Carrier State:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Fourth Event:	Carrier Zip:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>		Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Alcohol Test Given: <b>NO</b>		
Drug Test Given: <b>1 - NONE</b>		Number of Axles:
Total Occupants: <b>1</b>		HazMat Involvement:
Vehicle Year: <b>2008</b>		HazMat Placard:
Vehicle Make: <b>PONTIAC - PONT</b>		Placard #:
Vehicle Model: <b>G6</b>	Most Harmful Event: <b>33 - VEHICLE IN TRAFFIC</b>	HazMat Released?:
Vehicle Style: <b>4D</b>		Converter Dolly:
Vehicle Color: <b>SILVER - SIL</b>	Abg Switch Stat:	GVWR:
Vehicle Config: <b>01 - PASSENGER CAR</b>	Abg Deploy: <b>03 - NOT DEPLOYED</b>	Cit Chrg Code 1:
Vehicle Defect: <b>01 - NONE</b>		Citation Charge 1:
Vehicle Action: <b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>	Trapped: <b>1 - NOT TRAPPED/APPLICABLE</b>	
Tow: <b>1 - DRIVEN AWAY</b>	Ejection: <b>1 - NOT APPLICABLE</b>	Cit Chrg Code 2:
	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	Citation Charge 2:
Tow #:	Occpnt Protect: <b>03 - SHOULDER AND LAP BELT USED</b>	
Initial Trvl Dir: <b>04 - WEST</b>		Citation Charge 3:
Vision Obscured: <b>01 - NOT OBSCURED</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Citation Charge 4:
	Died at Scene: <b>01 - NOT APPLICABLE</b>	

**Accident Environment**

First Harmful Event Loc: <b>98 - OTHER (EXPLAIN IN NARRATIVE)</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>09 - REAR TO SIDE</b>	Environment: <b>01 - NONE APPARENT</b>
Light Conditions: <b>1 - DAYLIGHT</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	
	Type of Road Junc/Feat: <b>01 - NON-JUNCTION/NO SPECIAL FEATURE</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	
Type:	First Harmful Evt of Crash: <b>33 - VEHICLE IN TRAFFIC</b>
Workers Present:	

**Narrative**

UNIT 1 WAS ATTEMPTING TO BACK OUT OF A PARKING SPOT IN THE PARKING LOT OF RIDGEVIEW SCHOOL IN HOLSTEIN. UNIT 2 WAS CUTTING ACROSS PARKING SPACES HEADING WEST TO EXIT THE PARKING LOT. UNIT 1 DIDN'T SEE UNIT 2 AS IT HAD CUT THROUGH THE PARKING SPACES WHILE UNIT 1 WAS BACKING OUT. UNITS 1 AND 2 THEN COLLIDED, CAUSING DAMAGE TO THE REAR OF UNIT 1 AND THE FRONT DRIVERS SIDE OF UNIT 2.