

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: **18-8015**
 Date of Acc: **11/09/18**
 Time of Acc: **05:57** Hrs.
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**
 Officer: **ANDERSON FRED**
 Badge #: **47-2**
 Report Date: **11/09/2018**
 Officer Notified: **05:59** Hrs.
 Officer Arrived: **07:09** Hrs.
 Scene Investigated: **YES**

Report to All Drivers:
 Legal Intervention: **NO**
 Private Property: **NO**
 County: **IDA - 47**
 Acc Loc City: **HOLSTEIN - 3515**
 Acc Dir From City:
 Closest City:
 Miles From City:
 Road, Street, HWay:
 Definable Location:
 Milepost Number:

At Intersection with:
 Div HWay Trvl Dir:
 Distance 1:
 Direction 1:
 Distance 2:
 Direction 2:
 X-Coordinate: **00290902**
 Y-Coordinate: **04708682**
 Location Literal: **US 59**
 Description:

Unit 001

Driver Name - Last: **KURTZ**
 First: **RACHEL**
 Middle: **MARIE**
 City: **EARLY**
 State: **IA**
 Zip: **50535-7729**
 Suffix:
 Gender: **Female**
 Age: **30**
 CDL: **NO**
 License State: **IA**
 License Class: **C**
 License Endorsmnt:
 License Restrictions:
 Speed Limit: **55**
 Seating Position: **01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER**
 Driver Condition: **01 - APPARENTLY NORMAL**
 Alcohol Test Given: **NO**
 Drug Test Given: **1 - NONE**
 Total Occupants: **1**
 Vehicle Year: **2004**
 Vehicle Make: **PONTIAC - PONT**
 Vehicle Model: **GRM**
 Vehicle Style: **4D**
 Vehicle Color: **BLACK - BLK**
 Vehicle Config: **01 - PASSENGER CAR**
 Vehicle Defect: **01 - NONE**
 Vehicle Action: **03 - TURNING RIGHT**
 Tow: **1 - DRIVEN AWAY**
 Tow #:
 Initial Trvl Dir: **01 - NORTH**
 Vision Obscured: **01 - NOT OBSCURED**

Bus Use:
 Dvr Distractions: **02 - NOT DISTRACTED**
 Traffic Controls: **01 - NO CONTROLS PRESENT**
 Point of Init Impact: **11 - FRONT DRIVER SIDE CORNER**
 Most Damaged Area: **11 - FRONT DRIVER SIDE CORNER**
 Undrrid/Ovrid: **1 - NONE**
 Rpr/Rplc Cost: **\$1,500.00**
 Ext of Damage: **2 - MINOR DAMAGE**
 First Event: **11 - LOSS OF TRACTION**
 Second Event: **33 - VEHICLE IN TRAFFIC**
 Third Event:
 Fourth Event:
 Most Harmful Event: **33 - VEHICLE IN TRAFFIC**
 Abg Switch Stat:
 Abg Deploy: **03 - NOT DEPLOYED**
 Trapped: **1 - NOT TRAPPED/APPLICABLE**
 Ejection: **2 - NOT EJECTED**
 Ejection Path: **01 - NOT EJECTED/NOT APPLICABLE**
 Occpnt Protect: **03 - SHOULDER AND LAP BELT USED**
 Source of Trans: **01 - NOT TRANSPORTED**
 Died at Scene: **01 - NOT APPLICABLE**

Transported to: **NONE**
 Transported by: **NONE**
 Special Veh Func: **01 - NO SPECIAL FUNCTION**
 Emergency Status: **01 - NOT APPLICABLE**
 Cont. Circum., Dvr: **05 - DRIVING TOO FAST FOR CONDITIONS**
 Carrier Name:
 Carrier Address:
 Carrier City:
 Carrier State:
 Carrier Zip:
 Cargo Body Type: **01 - NOT APPLICABLE**
 Number of Axles:
 HazMat Involvement:
 HazMat Placard:
 Placard #:
 HazMat Released?:
 Converter Dolly:
 GVWR:
 Cit Chrg Code 1:
 Citation Charge 1:
 Cit Chrg Code 2:
 Citation Charge 2:
 Citation Charge 3:
 Citation Charge 4:

Unit 002

Driver Name - Last: REITZ	Bus Use:	Transported to: NONE
First: ASHLEY	Drvr Distractions: 02 - NOT DISTRACTED	Transported by: NONE
Middle: ELAINE	Traffic Controls: 01 - NO CONTROLS PRESENT	Special Veh Func: 01 - NO SPECIAL FUNCTION
City: IDA GROVE	Point of Init Impact: 09 - MIDDLE DRIVER SIDE	Emergency Status: 01 - NOT APPLICABLE
State: IA	Most Damaged Area: 09 - MIDDLE DRIVER SIDE	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Zip: 51445	Undrrid/Ovrid: 1 - NONE	
Suffix:	Rpr/Rplc Cost: \$1,500.00	Carrier Name:
Gender: Female	Ext of Damage: 2 - MINOR DAMAGE	Carrier Address:
Age: 22	First Event: 33 - VEHICLE IN TRAFFIC	Carrier City:
CDL: NO	Second Event:	Carrier State:
License State: IA	Third Event:	Carrier Zip:
License Class: C	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Endorsmnt: B	Most Harmful Event: 33 - VEHICLE IN TRAFFIC	Number of Axles:
License Restrictions: B	Abg Switch Stat:	HazMat Involvement:
Speed Limit: 55	Abg Deploy: 03 - NOT DEPLOYED	HazMat Placard:
Seating Position: 01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER	Trapped: 1 - NOT TRAPPED/APPLICABLE	Placard #:
Driver Condition: 01 - APPARENTLY NORMAL	Ejection: 2 - NOT EJECTED	HazMat Released?:
Alcohol Test Given: NO	Ejection Path: 01 - NOT EJECTED/NOT APPLICABLE	Converter Dolly:
Drug Test Given: 1 - NONE	Occpnt Protect: 03 - SHOULDER AND LAP BELT USED	GVWR:
Total Occupants: 1	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Year: 2010	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Make: CHEVROLET - CHEV		Cit Chrg Code 2:
Vehicle Model: MAL		Citation Charge 2:
Vehicle Style: 4D		Citation Charge 3:
Vehicle Color: TAN - TAN		Citation Charge 4:
Vehicle Config: 01 - PASSENGER CAR		
Vehicle Defect: 01 - NONE		
Vehicle Action: 98 - OTHER (EXPLAIN IN NARRATIVE)		
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir: 04 - WEST		
Vision Obscured: 01 - NOT OBSCURED		

Accident Environment

First Harmful Event Loc: 01 - ON ROADWAY	Roadway Characteristics
Manner of Crash/Collision: 05 - BROADSIDE (FRONT TO SIDE)	Environment: 02 - WEATHER CONDITION
Light Conditions: 4 - DARK, ROADWAY LIGHTED	Roadway: 02 - SURFACE CONDITION (E.G., WET, ICY)
Weather Conditions: 07 - SNOW	Type of Road Junc/Feat: 04 - DRIVEWAY ACCESS (WITHIN)
Surface Conditions: 04 - SNOW	FRA No.:
Workzone Related: NO	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 33 - VEHICLE IN TRAFFIC
Type:	
Workers Present:	

Narrative

Unit #1 was northbound on Highway 59. Unit #2 was stopped in the VT Industries parking lot exit waiting on traffic. Unit #1 attempted a right hand turn into the VT Industries parking lot. Due to the road surface conditions, Unit #1 was unable to stop and did slide into the drivers rear door and quarter panel causing minor damage to both vehicles.

Diagram

