

**INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT**

Case Number: **18-8106**  
 Date of Acc: **11/11/18**  
 Time of Acc: **20:54** Hrs.  
 Name of Agency: **IDA COUNTY SHERIFF'S OFFICE**  
 Officer: **EHLERS ALEX**  
 Badge #: **47-10**  
 Report Date: **11/11/2018**  
 Officer Notified: **21:30** Hrs.  
 Officer Arrived: **21:30** Hrs.  
 Scene Investigated: **NO**

Report to All Drivers:  
 Legal Intervention: **NO**  
 Private Property: **NO**  
 County: **IDA - 47**  
 Acc Loc City:  
 Acc Dir From City:  
 Closest City:  
 Miles From City:  
 Road, Street, HWay:  
 Definable Location:  
 Milepost Number:

At Intersection with:  
 Div HWay Trvl Dir:  
 Distance 1:  
 Direction 1:  
 Distance 2:  
 Direction 2:  
 X-Coordinate: **00295685**  
 Y-Coordinate: **04691718**  
 Location Literal: **US 59**  
 Description:

**Unit 001**

Driver Name - Last: <b>LINDGREN</b>	Bus Use:	Transported to: <b>N/A</b>
First: <b>HUNTER</b>		
Middle: <b>ANDREW</b>	Dvr Distractions: <b>02 - NOT DISTRACTED</b>	Transported by: <b>N/A</b>
City: <b>BATTLE CREEK</b>		
State: <b>IA</b>	Traffic Controls: <b>01 - NO CONTROLS PRESENT</b>	Special Veh Func: <b>01 - NO SPECIAL FUNCTION</b>
Zip: <b>51006-0000</b>		
Suffix:	Point of Init Impact: <b>01 - FRONT PASSENGER SIDE CORNER</b>	Emergency Status: <b>01 - NOT APPLICABLE</b>
Gender: <b>Male</b>	Most Damaged Area: <b>01 - FRONT PASSENGER SIDE CORNER</b>	Cont. Circum., Dvr: <b>88 - NO IMPROPER ACTION</b>
Age: <b>21</b>	Undridd/Ovrid: <b>1 - NONE</b>	
CDL: <b>YES</b>	Rpr/Rplc Cost: <b>\$4,000.00</b>	
License State: <b>IA</b>	Ext of Damage: <b>2 - MINOR DAMAGE</b>	
License Class: <b>A</b>	First Event: <b>31 - ANIMAL</b>	
License Endorsmnt:		Carrier Name:
License Restrictions:		Carrier Address:
Speed Limit: <b>55</b>	Second Event:	Carrier City:
Seating Position: <b>01 - 1ST ROW: LEFT SIDE/MOTORCYCLE DRIVER</b>	Third Event:	Carrier State:
Driver Condition: <b>01 - APPARENTLY NORMAL</b>	Fourth Event:	Carrier Zip:
Alcohol Test Given: <b>NO</b>		Cargo Body Type: <b>01 - NOT APPLICABLE</b>
Drug Test Given: <b>1 - NONE</b>		
Total Occupants: <b>1</b>	Most Harmful Event: <b>31 - ANIMAL</b>	Number of Axles:
Vehicle Year: <b>2005</b>	Abg Switch Stat:	HazMat Involvement:
Vehicle Make: <b>FORD - FORD</b>	Abg Deploy: <b>03 - NOT DEPLOYED</b>	HazMat Placard:
Vehicle Model: <b>F25</b>		Placard #:
Vehicle Style: <b>PK</b>	Trapped: <b>1 - NOT TRAPPED/APPLICABLE</b>	HazMat Released?:
Vehicle Color: <b>WHITE - WHI</b>	Ejection: <b>2 - NOT EJECTED</b>	Converter Dolly:
Vehicle Config: <b>02 - FOUR-TIRE TRUCK (PICK-UP)</b>	Ejection Path: <b>01 - NOT EJECTED/NOT APPLICABLE</b>	GVWR:
Vehicle Defect: <b>01 - NONE</b>	Occpnt Protect: <b>03 - SHOULDER AND LAP BELT USED</b>	Cit Chrg Code 1:
Vehicle Action: <b>01 - MOVEMENT ESSENTIALLY STRAIGHT</b>		Citation Charge 1:
Tow: <b>1 - DRIVEN AWAY</b>		Cit Chrg Code 2:
Tow #:		Citation Charge 2:
Initial Trvl Dir: <b>04 - WEST</b>		Citation Charge 3:
Vision Obscured: <b>01 - NOT OBSCURED</b>	Source of Trans: <b>01 - NOT TRANSPORTED</b>	Citation Charge 4:
	Died at Scene: <b>01 - NOT APPLICABLE</b>	

**Accident Environment**

First Harmful Event Loc: <b>01 - ON ROADWAY</b>	<b>Roadway Characteristics</b>
Manner of Crash/Collision: <b>01 - NON-COLLISION (SINGLE VEHICLE)</b>	Environment: <b>06 - ANIMAL IN ROADWAY</b>
Light Conditions: <b>5 - DARK, ROADWAY NOT LIGHTED</b>	Roadway: <b>01 - NONE APPARENT</b>
Weather Conditions: <b>01 - CLEAR</b>	
	Type of Road Junc/Feat: <b>01 - NON-JUNCTION/NO SPECIAL FEATURE</b>
Surface Conditions: <b>01 - DRY</b>	
	FRA No.:
Workzone Related: <b>NO</b>	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: <b>31 - ANIMAL</b>
Type:	
Workers Present:	

**Narrative**

Unit 1 was heading West on Hwy 175 near the intersection of Jasper Ave. Unit 1 struck a deer on the passenger's side front fender. Vehicle was then drove to the residence and a report was done at the residence.