

INFORMATION FROM THE INVESTIGATING OFFICERS REPORT OF MOTOR VEHICLE ACCIDENT

Case Number: 19-121	Report to All Drivers:	At Intersection with:
Date of Acc: 01/05/19	Legal Intervention: NO	Div HWay Trvl Dir:
Time of Acc: 18:39 Hrs.	Private Property: NO	Distance 1:
Name of Agency: IDA COUNTY SHERIFF'S OFFICE	County: IDA - 47	Direction 1:
Officer: VAN EGDOM BRADY	Acc Loc City:	Distance 2:
Badge #: 47-5	Acc Dir From City:	Direction 2:
Report Date: 01/06/2019	Closest City:	X-Coordinate: 00287992
Officer Notified: 10:20 Hrs.	Miles From City:	Y-Coordinate: 04687677
Officer Arrived: 10:30 Hrs.	Road, Street, HWay:	Location Literal: 270TH ST
Scene Investigated: NO	Definable Location:	Description:
	Milepost Number:	

Unit 001

Driver Name - Last: AWREY	Bus Use:	Transported to:
First: KYLE		
Middle: SCOTT	Drvtr Distractions: 02 - NOT DISTRACTED	Transported by:
City: IDA GROVE	Traffic Controls:	Special Veh Func:
State: IA	Point of Init Impact:	Emergency Status:
Zip: 51445	Most Damaged Area:	Cont. Circum., Drvr: 88 - NO IMPROPER ACTION
Suffix:	Undrrid/Ovrid:	
Gender: Male	Rpr/Rplc Cost: \$1,500.00	Carrier Name:
Age: 22	Ext of Damage:	Carrier Address:
CDL: NO	First Event:	Carrier City:
License State: IA	Second Event:	Carrier State:
License Class: D	Third Event:	Carrier Zip:
License Endorsmnt: 1 - TRK - TRCTR SEMI-TRAILER	Fourth Event:	Cargo Body Type: 01 - NOT APPLICABLE
License Restrictions:	Most Harmful Event:	Number of Axles:
Speed Limit:	Abg Switch Stat:	HazMat Involvement:
Seating Position:	Abg Deploy:	HazMat Placard:
Driver Condition:	Trapped:	Placard #:
Alcohol Test Given: NO	Ejection:	HazMat Released?:
Drug Test Given: 1 - NONE	Ejection Path:	Converter Dolly:
Total Occupants: 1	Occpnt Protect:	GVWR:
Vehicle Year: 2010	Source of Trans: 01 - NOT TRANSPORTED	Cit Chrg Code 1:
Vehicle Make: FORD - FORD	Died at Scene: 01 - NOT APPLICABLE	Citation Charge 1:
Vehicle Model: FUS		Cit Chrg Code 2:
Vehicle Style: SD		Citation Charge 2:
Vehicle Color: SILVER - SIL		Citation Charge 3:
Vehicle Config: 01 - PASSENGER CAR		Citation Charge 4:
Vehicle Defect:		
Vehicle Action:		
Tow: 1 - DRIVEN AWAY		
Tow #:		
Initial Trvl Dir:		
Vision Obscured:		

Accident Environment

First Harmful Event Loc:	Roadway Characteristics
Manner of Crash/Collision:	Environment:
Light Conditions:	Roadway:
Weather Conditions:	Type of Road Junc/Feat:
Surface Conditions:	FRA No.:
Workzone Related:	Horizontal Alignment:
Activity:	Vertical Alignment:
Location:	First Harmful Evt of Crash: 31 - ANIMAL
Type:	
Workers Present:	

Narrative

UNIT 1 WAS TRAVELING WEST ON 270TH ST. NEAR THE INTERSECTION OF EAGLE AVENUE. A DEER THEN EXITED THE NORTH DITCH AND ENTERED THE ROADWAY. UNIT 1 WAS UNABLE TO AVOID THE DEER, STRIKING THE DEER WITH THE FRONT PORTION OF THE VEHICLE.

Diagram

